

# ANNUAL SURVEYS.

No. 185 Survey held at London Date 2<sup>nd</sup> to 7<sup>th</sup> Aug<sup>t</sup> 18 69

on the Iron Ship "White Eagle" Master W. Andrew

Tonnage 878 Built at Glasgow When built 1855

By whom built        Owners Bilbe

Port belonging to London Destined Voyage Adelaide

If Surveyed Afloat or in Dry Dock Greens Upper dry dock

Last Survey, No. 6520 Port of Iron Classed A.1  
S.S. 1<sup>st</sup> 1. 68. 9. 68.

The present Condition of the

Decks	Treenails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cem</u> When put on <u>X</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined.  
Bottom cleaned, and coated with patent composition.  
Is now in good, and efficient condition, and in our opinion  
eligible to remain as Classed.

Committee's Minute 20<sup>th</sup> August 1869

Character assigned A 1

Wm. Moberly.  
J. H. Turner  
Certificate (if required).

No. 1017 Survey held at London Date 5<sup>th</sup> to 11<sup>th</sup> Aug<sup>t</sup> 18 69

on the Iron Ship "Syria" Master E. Gooch

Tonnage 1010 Built at Dunfermline When built 1868 6 mo

By whom built Pile Owners J. Nourse

Port belonging to London Destined Voyage Calcutta

If Surveyed Afloat or in Dry Dock Victoria Pontoon

Last Survey, No. 6370 Port of Iron Classed A.1  
6. 68.

The present Condition of the

Decks	Treenails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1868</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined.  
Inside from Hold Beam Stringer plate, to turn of Bilge  
cleaned, and painted, Bottom cleaned, and coated with paint and Tallow.  
Is now in good, and efficient condition, and in our opinion eligible to remain as Classed.

Committee's Minute 20<sup>th</sup> August 1869

Character assigned A 1

Wm. Moberly.  
Sam. Lapham  
Certificate (if required).