

# ANNUAL SURVEYS.

No. 2 Survey held at London Date 13 August 14<sup>th</sup> 18 69  
 on the Iron Screw Steamer "Valdemar" Master J. Frederik Rasmussen  
 Tonnage 439 Built at Newcastle When built 1866 11 mo.  
 By whom built Leslie Owners United Steam Co. Copenhagen  
 Port belonging to London Destined Voyage Baltic  
 If Surveyed Afloat or in Dry Dock Lincolnton Dry Dock

Last Survey, No. 5326 Port of Nov. Classed B. 1.

The present Condition of the

Decks <u>Good</u>	Treenails <u>Rivets</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>Strong</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>Good</u>	Keelsons <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>Good</u> When put on <u>1867</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good as far as can be seen

The bottom was scraped, and coated with two coats of Treake & Sons' Black Varnish. - This vessel, as far as can be seen, is in good condition and in my opinion eligible to remain as classed B. 1.

Committee's Minute 24<sup>th</sup> August 18 69 Wm. J. Bone

Character assigned B. 1. M.

Certificate (if required).

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18 \_\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_

Character assigned \_\_\_\_\_



© 2019

Lloyd's Register

Certificate (if required).