

ANNUAL SURVEYS.

Rec 11/9/69
th 20

No. 21985 Survey held at Liverpool Date July 20 & 23 18 69
 on the Iron S "Baroda" Master J. Fuller
 Tonnage 1364 Built at Belfast When built 1864 - 4 ms.
 By whom built Harland Owners Brookley & Co
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Clarence Graving Dock

Last Survey, No. 6600 Port of Iron Classed 1A 1
 (SP. No. 1-150) 10.68

The present Condition of the

Decks	Ironails <u>Rivets</u>	Windlass and Capstan <u>Good & efficient</u>
Waterways	Breasthooks and Stemson	Pumps <u>where seen</u>
Comings	Transoms, Pointers, and Crutches	Boats " "
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. " "
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails " "
Planksheers	Keelsons	Anchors No. of " "
Sheerstrakes	Clamps and Shelves	Cables " "
Topsides	Ceiling	Hawsers and Warps " "
Wales	Rudder	Standing & Running Rigging " "
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>64</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Satisfactory

The bottom scraped & coated with composition. Is now in an efficient condition & in my opinion eligible to remain as classed

Committee's Minute Liverpool 31st August 1869
 Character assigned A 1 B.W. E. C. Wheeler
 Certificate (if required).

No. 6459 Survey held at Liverpool Date Aug 17 & 19 18 69
 on the (Iron) S "Argowan" Master A. Kerr
 Tonnage 1203 Built at Greenock When built 1867 - 9 ms.
 By whom built Steele Owners Adam & Co
 Port belonging to Greenock Destined Voyage India
 If Surveyed Afloat or in Dry Dock Clarence Graving Dock

Last Survey, No. 6459 Port of Iron Classed 1A 2
 8.68

The present Condition of the

Decks	Ironails <u>Rivets</u>	Windlass and Capstan <u>Good & efficient</u>
Waterways	Breasthooks and Stemson	Pumps <u>where seen</u>
Comings	Transoms, Pointers, and Crutches	Boats " "
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. " "
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails " "
Planksheers	Keelsons	Anchors No. of " "
Sheerstrakes	Clamps and Shelves	Cables " "
Topsides	Ceiling	Hawsers and Warps " "
Wales	Rudder	Standing & Running Rigging " "
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>67</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Satisfactory

The bottom scraped & coated with composition. Is now in an efficient condition & in my opinion eligible to remain as classed.

Committee's Minute Liverpool 31st August 1869
 Character assigned A 1 B.W. E. C. Wheeler
 Certificate (if required).

Baroda
-21985-
"Ardgawari"



© 2019

Lloyd's Register
Foundation