

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. *988* No. *1* Survey held at *London* Date, first Survey *10th Aug^t* Last Survey *16th Aug^t* 18 *69*
 on the *S. S. "Miranda"* Master *Partridge*
 Tonnage *819* built at *Newcastle* When built *1865* 3 Mo
 By whom built *Palmer* Owners *London Steam Ship Co^e*
 Port belonging to *London* Destined Voyage *Mediterranean*
 If Surveyed Afloat or in Dry Dock *Victoria Pontoons*
 Last Survey, No. *6485* Port *Iron* Classed *A. 1*
 REPAIRS, &c. *now done* *S. S. No 1. 67* *8. 68*

The Limbers, and Tank covers removed Fore, and Aft, on both sides. Tanks cleaned out, and Asph^d found adhering satisfactorily to the Iron. Inside scraped, and painted from turn of Bilge to Upper deck stringer plate. Bottom cleaned, and coated with two coats of paint, and one of Tallow. Repaired steering gear, and Rebrushed braces to Rudder.

Present Condition of the

Decks	Greenails <i>Rivets</i>	Windlass and Capstan <i>Good</i>
Waterways	Breasthooks and Stemson	Pumps <i>"</i>
Comings	Transoms, Pointers, and Crutches	Boats <i>"</i>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <i>"</i>
Lower Deck Beams & Fastenings	Ditto <i>Ditto</i> at other places	Condition, how ascertained <i>seen from the deck</i>
Planksheers	Keelsons	Sails <i>"</i>
Sheerstrakes	Clamps and Shells	Anchors No. of <i>Good</i>
Topsides	Ceiling	Cables <i>and</i>
Wales	Rudder	Hawsers and Warps <i>Sufficient</i>
Plank (Bottom) and Counter	Copper <i>Asph</i> When put on <i>1865</i>	Standing & Running Rigging
Engine Room Skylights <i>Good</i>	Caulking of	
Coal Bunker, Openings, Lids, &c. <i>Good</i>	Bottom, Deck, & Waterways <i>Good when tested</i>	
General Observations and Opinion,	Scuppers <i>Good</i>	Cargo and Main Hatchways <i>Good</i>
		Hatches <i>Good</i>

Is now in Good, and Efficient condition, and in our opinion eligible to remain as Classed, and to be marked

(S. S. No 2. 69)

The Amount of Entry Fee.....£ - - - is received by me,

Special..... 2 : 2

Certificate (if required) - - -

Committee's Minute *3rd September* 18 *69*

Character assigned *A. 1*

Jm Moverly.
Saml. Laphorn



© 2019

Lloyd's Register Foundation

IRON 444-0376