7389

~~3038~~

REPORT of SURVEY for REPAIRS.

Change of Owners

No. in Reg. Book. 2 — No. — Survey held at London — Date, first Survey 16th Sept. Last Survey 17th Sept. 1869.

on the Screw Steam. "Valdemar" Master T. Juhl

Tonnage 646 439 built at Newcastle When built 1866 - 11 mo

By whom built Leslie Owners a United Steam Navig. Co. Company

Port belonging to Copenhagen Destined Voyage Baltic

If Surveyed Afloat or in Dry Dock Deptford Green Dry Dock and afloat in the River

Last Survey, No. 7301 Port Iron Dan Classed 3/1

REPAIRS, &c. 8.69.

For Damage

Several of the butts in the plat of bottom, and around the Bilges, from fore Mast to Main Hatch, that were found more or less strained, have now been caulked. Bottom coated with Black Varnish.

	Cwt.	qrs.	lbs.	
1 Steam Anchor including stock	7	1	0	3
1 Sledge. — — — lbs	4	3	2	Now supplied.
Hawser. 8 ins. 90 fms.				3

The Master's attention was drawn to this Vessel being heavy due for the 2 S.P.O. but such was not entertained.

Present Condition of the

Decks	Where seen Good	~~Treenails~~ Rivets	Windlass and Capstan Good
Waterways		Breasthooks ~~and Stemson~~	Pumps —
Comings		~~Transoms, Pointers, and Crutches~~	Boats —
Upper Deck Beams & Fastenings		~~Timbers of the Frame at the openings~~	Masts, Yards, &c. —
Lower Deck Beams & Fastenings		Ditto ~~Ditto~~ at other places	Condition, how ascertained Seen from the deck
Planksheers		Keelsons	Sails
Sheerstrakes		~~Clamps and Shelfs~~	Anchors No. of Good
Topsides		Ceiling	Cables and
Wales		Rudder	Hawsers and Warps Sufficient
~~Plank~~ (Bottom) and Counter		~~Copper~~ Iron When put on 1867	Standing & Running Rigging
		Caulking of Bottom, Deck, & Waterways 3	Where seen Good 3

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations and Opinion,

Now in good and efficient condition; and in my opinion Eligible to remain as Classed 3/1.

The Amount of Entry Fee.....£ 1 : — : — } is received by me.

Special..... 1/2 : 1/2 : — }

Damage Certificate (if required) 1/2 : 1/2 : — }

Committee's Minute 24th September 1869

Character assigned [3/1] Mch

W W Inches

© 2019 Lloyd's Register Foundation

IRON444-0438