

No.

Survey held at

London ⁷³⁹⁹Date 23rd Sept 29th 1869

30401

2 on the Iron Barque *Barraconsa*

Master

Tonnage 610

Built at Liverpool

When built 1864 - 7 mo

By whom built

Owners Hilley & Co.

Port belonging to Liverpool

Destined Voyage

If Surveyed Afloat or in Dry Dock "Downs" dry dock

Last Survey, No.

6253

Port of

Ror.

Classed

A.1.

S.S. no 1/58

The present Condition of the

Decks

good

Treenails

Rivets

two renewed

good

Windlass and Capstan

in good order

Waterways

11

Breasthooks and Stemson

11

Pumps

11

mings

11

Transoms, Pointers, and Crutches

11

Boats

11

Upper Deck Beams & Fastenings

11

Timbers of the Frame at the Openings

11

Masts, Yards, &c.

11

Lower Deck Beams & Fastenings

11

Ditto ditto at other places

11

Sails

11

Planksheers

11

Keelsons

11

Anchors No. of

3 1

11

Heerstrakes

11

Clamps and Shelves

11

Cables

11

Topsides

11

Ceiling

11

Hawsers and Warps

11

Wales

11

Rudder *efficient*

11

Standing & Running Rigging

11

Plank (Bottom) and Counter

11

Copper

When put on

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good.

Renewed two rivets on the Starboard side and tested others.


She appears to be in good condition and is in my opinion
 entitled to remain as class'd A.1.

Committee's Minute

5th October 1869

Character assigned

A.1



Samuel Wilson

Certificate (if required).

IRON 445-0009