

(Iron) 7579
ANNUAL SURVEYS.

30574

113 No. Survey held at London Date 8th to 11th December 1869
on the Barque "Pecapolis" Master L. Almond
Tonnage 632 Built at Lunderland When built 1868 & mo.
By whom built Pile Owners J. B. Walker
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock Limekiln Dry Dock

Last Survey, No. 6503 Port of Iron Classed A. 1
(9. 68)

The present Condition of the

Decks	<u>Good where seen</u>	Treenails <u>Rivets</u>	<u>Good where seen</u>	Windlass and Capstan	<u>Good and sufficient</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper <u>Cement</u> When put on <u>1868</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

The bottom now cleaned; and coated with two coats of Oxide of Iron, one of White Zinc paint, and two coats of Gibbs' patent Antifouling Soap.

Is in good condition and in my opinion fit to remain as classed (viz), A. 1

Committee's Minute 17th December 1869

J. M. J. Bone

Character assigned A. 1 MAK

Certificate (if required)

No. Survey held at Date 18
on the Master
Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute 18

Character assigned

Certificate (if required).