

ANNUAL SURVEYS.

No. 3071 Survey held at Glasgow Date 17th to 31st Dec^r 1869
 on the Iron B^t Corrientes Master Johnson
 Tonnage 590 Built at Sunduland When built 1864 1 mo
 By whom built Ormal Owners Shallerson &
 Port belonging to Liverpool Destined Voyage By Sea Francisco
 If Surveyed Afloat or in Dry Dock Super. Stephen's Slipway & Kingston Dock

Last Survey, No. 6710 Port of Iron Classed A1 SS No 1 B
 1.66

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats <u>and</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons Do Do at other places <u>Where</u>	Sails <u>supp</u>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables <u>Where</u>
Topsides	Rudder <u>seen</u>	Hawsers and Warps
Wales	Copper <u>seen</u> When put on	Standing & Running Rigging <u>seen</u>
Plank (Bottom) and Counter <u>seen</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

The bottom outside cleaned and recoated. She is in good and efficient condition eligible to remain as classed A1

Committee's Minute 11th January 1870

Character assigned A 1

H. Munford

Certificate (if required)

149 No. 3071 Survey held at Glasgow Date 24th Dec^r 1869
 on the Iron B^t Onyx Master Hatch
 Tonnage 420 Built at Sunduland When built 1864 11 mo
 By whom built Laing Owners Wheatley
 Port belonging to Sunduland Destined Voyage By Sea
 If Surveyed Afloat or in Dry Dock Bowley & Carter's Slipway

Last Survey, No. 7613 Port of Iron Classed B1 SS No 1 B
 1.66

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats <u>and</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings <u>Where</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons Do Do at other places	Sails <u>supp</u>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables <u>Where</u>
Topsides	Rudder <u>seen</u>	Hawsers and Warps
Wales	Copper <u>seen</u> When put on <u>see frame</u>	Standing & Running Rigging <u>seen</u>
Plank (Bottom) and Counter <u>seen</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

Called the owner's attention to the special survey. Now apparently due this the owner informed me was recently held in Sunduland which I find to be correct. as far as could be seen upon an ordinary survey. she appears in good and efficient condition eligible to remain as classed

Committee's Minute 11th January 1870

Character assigned B1

H. Munford
 Certificate (if required)