

7648 ANNUAL SURVEYS.

Rec 13/1/70

No. 9774 Survey held at Sunderland Date Nov 29th to Dec 1st 1869
 on the Iron BK Alcestis Master Richards
 Tonnage 359 Built at Sunderland When built 1868 S. Abo
 By whom built Cliff, Hounsey & Co Owners Penney & Co
 Port belonging to Moreham Destined Voyage _____
 If Surveyed Afloat or in Dry Dock By Sost

Last Survey, No. 6270 Port of Iron - Sunderland Classed FA 1
at present Bottom Painted 6.68

The present Condition of the

Decks	Treenails <u>Rivets</u>	Windlass and Capstan <u>W</u> <u>Good</u>
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails <u>Well found</u>
Planksheers	Keelsons	Anchors No. of <u>3 No. St. & Kite</u>
Sheerstrakes	Clamps and Shelves	Cables <u>Complete</u>
Topsides	Ceiling	Hawsers and Warps <u>Sufficient</u>
Wales	Rudder	Standing & Running Rigging <u>Good</u>
Plank (Bottom) and Counter	Copper <u>When put on</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good

Is now in an efficient state and in my opinion entitled to remain as classed
Leahouse Martindale

Committee's Minute 14th January 1870

Character assigned A 1

Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____

on the _____ Master _____

Tonnage _____ Built at _____ When built _____

By whom built _____ Owners _____

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>When put on</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18____

Character assigned _____

Certificate (if required).