

ANNUAL SURVEYS.

No. 172 Survey held at London Date 1st Jan^y - 26th Jan^y 1870
 on the Iron Ship "Oriana" Master Currie
 Tonnage 997 Built at Grunoche When built 1864
 By whom built Scott Owners W. Orr
 Port belonging to Grunoche Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Grun's Upper Dry Dock.

Last Survey, No. 6846

Port of Iron

Classed A1
 (S. S. No. 1-68.)
 1, 69.

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Greenails Rivets

Breasthooks and Stomson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper Laminated When put on 1864.

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Good and efficient.

Good and

sufficient.

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Outside cleaned down and painted, and bottom tallowed. Rudder pintles bushed.

Is now in good and efficient condition, and fit in my opinion to remain as classed - A1.

Committee's Minute 28th January 18 70

Character assigned A1

J. H. Eastlake.

Certificate (if required)

No. 912 Survey held at London Date 20th Jan^y - 27th Jan^y 1870
 on the Iron Ship "Superb" Master E. Jones
 Tonnage 1451 Built at London When built 1866
 By whom built Green Owners R. L. H. Green
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Green's Upper Dry Dock.

Last Survey, No. 6958

Port of Iron

Classed A1
 3, 69.

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Greenails Rivets

Breasthooks and Stomson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper Laminated When put on 1866.

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Good and efficient.

Good and

sufficient.

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Outside cleaned down and painted, bottom coated with

Gibbs's Composition.

Is now in good and efficient condition, and fit in my opinion to remain as classed - A1.

Committee's Minute 28th January 18 70

Character assigned A1

J. H. Eastlake.

Certificate (if required)