

ANNUAL SURVEYS.

No. 22191 Survey held at Liverpool Date May 22 to July 8 18 70
 on the Iron Ship "Ellen Lamb" Master Braithwaite
 Tonnage 499 Built at Glasgow When built 1867 - 3 mo
 By whom built Jobie Owners Edward Hinton & Co
 Port belonging to Lpool Destined Voyage Singapore
 If Surveyed Afloat or in Dry Dock Afloat & in Clarence Graving dock

Last Survey, No. 6952 Port of Iron Classed 3-69

The present Condition of the

Decks	Freeboards <u>Pirats</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>Good &</u>
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings	Ditto ditto at other places <u>seen</u>	Sails <u>where</u>
Planksheers	Keelsons	Anchors No. of <u>seen</u>
Sheerstrakes	Clamps and Shelves	Cables <u>seen</u>
Topsides	Ceiling	Hawsers and Warps <u>seen</u>
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on <u>67</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Satisfactory

The bottom scraped & coated with paint. I am in an efficient condition & in my opinion eligible to remain as Classed -

Committee's Minute Liverpool 15th February 1870

E. C. Wheeler

Character assigned A 1

Certificate (if required).

No. 107 Survey held at Liverpool Date Feb - 2 to 8 18 70
 on the Iron Ship "Cendasserin" Master Potts
 Tonnage 1419 Built at Belfast When built 1866 - 8 mo
 By whom built Harland Owners J. & S. Brocklebank
 Port belonging to Lpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Afloat & in Clarence Graving dock

Last Survey, No. 6539 Port of Iron Classed 3-69
(SS 1-60)

The present Condition of the

Decks	Freeboards <u>Pirats</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>Good &</u>
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings	Ditto ditto at other places <u>seen</u>	Sails <u>where</u>
Planksheers	Keelsons	Anchors No. of <u>seen</u>
Sheerstrakes	Clamps and Shelves	Cables <u>seen</u>
Topsides	Ceiling	Hawsers and Warps <u>seen</u>
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on <u>66</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Satisfactory

The bottom scraped & coated with McInnes' paint. I am in an efficient condition & in my opinion eligible to remain as Classed -

Committee's Minute Liverpool 15th February 1870

E. C. Wheeler

Character assigned A 1

Certificate (if required).

Ellen Lamb
22.191
" 7
Verasserin