

# ANNUAL SURVEYS.

No. 271 Survey held at London Date 7<sup>th</sup> Feb'y 1870  
 on the Iron Ship Glenavon Master J. Henderson  
 Tonnage 830 Built at Aberdeen When built 1868  
 By whom built Hood Owners Gow & Co.  
 Port belonging to Aberdeen Destined Voyage Shanghai  
 If Surveyed Afloat or in Dry Dock Bull head dry dock

Last Survey, No. 6653 Port of Iron. Classed A.1.

The present Condition of the

|                               |             |                                      |             |                            |                      |
|-------------------------------|-------------|--------------------------------------|-------------|----------------------------|----------------------|
| Decks                         | <u>good</u> | Freemasts                            | <u>good</u> | Windlass and Capstan       | <u>in good order</u> |
| Waterways                     | <u>"</u>    | Breasthooks and Stemson              | <u>"</u>    | Pumps                      | <u>"</u>             |
| Comings                       | <u>"</u>    | Transoms, Pointers, and Crutches     | <u>"</u>    | Boats                      | <u>"</u>             |
| Upper Deck Beams & Fastenings | <u>"</u>    | Timbers of the Frame at the Openings | <u>"</u>    | Masts, Yards, &c.          | <u>"</u>             |
| Lower Deck Beams & Fastenings | <u>"</u>    | Ditto ditto at other places          | <u>"</u>    | Sails                      | <u>"</u>             |
| Planksheers                   | <u>"</u>    | Keelsons                             | <u>"</u>    | Anchors No. of <u>3</u>    | <u>"</u>             |
| Sheerstrakes                  | <u>"</u>    | Clamps and Shelves                   | <u>"</u>    | Cables                     | <u>"</u>             |
| Topsides                      | <u>"</u>    | Ceiling                              | <u>"</u>    | Hawsers and Warps          | <u>"</u>             |
| Wales                         | <u>"</u>    | Rudder <u>efficient</u>              | <u>"</u>    | Standing & Running Rigging | <u>"</u>             |
| Plank (Bottom) and Counter    | <u>"</u>    | Copper                               | When put on |                            |                      |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

Clean'd the bottom and recoated it with McQuinn's composition  
I am of opinion she is entitled to remain as class'd  
 Committee's Minute 18<sup>th</sup> February 1870 A.1.  
 Character assigned A.1.

Certificate (if required)

No. 399 Survey held at London Date 7<sup>th</sup> Feb'y 1870  
 on the Iron Ship Henderson Master Francis Worsby  
 Tonnage 833 Built at Port Glasgow When built 1863  
 By whom built Reed Owners British & E. S. Comp'y  
 Port belonging to Liverpool Destined Voyage Shanghai  
 If Surveyed Afloat or in Dry Dock King & Queen Dry Dock

Last Survey, No. 6284 Port of Iron. Classed A.1. 53/11 68  
2.68

The present Condition of the

|                               |             |                                      |             |                            |                      |
|-------------------------------|-------------|--------------------------------------|-------------|----------------------------|----------------------|
| Decks                         | <u>good</u> | Freemasts                            | <u>good</u> | Windlass and Capstan       | <u>in good order</u> |
| Waterways                     | <u>"</u>    | Breasthooks and Stemson              | <u>"</u>    | Pumps                      | <u>"</u>             |
| Comings                       | <u>"</u>    | Transoms, Pointers, and Crutches     | <u>"</u>    | Boats                      | <u>"</u>             |
| Upper Deck Beams & Fastenings | <u>"</u>    | Timbers of the Frame at the Openings | <u>"</u>    | Masts, Yards, &c.          | <u>"</u>             |
| Lower Deck Beams & Fastenings | <u>"</u>    | Ditto ditto at other places          | <u>"</u>    | Sails                      | <u>"</u>             |
| Planksheers                   | <u>"</u>    | Keelsons                             | <u>"</u>    | Anchors No. of <u>3</u>    | <u>"</u>             |
| Sheerstrakes                  | <u>"</u>    | Clamps and Shelves                   | <u>"</u>    | Cables                     | <u>"</u>             |
| Topsides                      | <u>"</u>    | Ceiling                              | <u>"</u>    | Hawsers and Warps          | <u>"</u>             |
| Wales                         | <u>"</u>    | Rudder <u>efficient</u>              | <u>"</u>    | Standing & Running Rigging | <u>"</u>             |
| Plank (Bottom) and Counter    | <u>"</u>    | Copper                               | When put on |                            |                      |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Clean'd the bottom and recoated it.  
I am of opinion she is entitled to remain as class'd  
 Committee's Minute 18<sup>th</sup> February 1870 A.1.  
 Character assigned A.1.

Certificate (if required).



Glenavon, Co.  
1/10/1880

7



© 2019

Lloyd's Register  
Foundation