

ANNUAL SURVEYS.

No. 163 Survey held at London Date 23rd Feb - 3rd March 1870
 on the Iron Ship "Knight Errant" Master J. Jackson
 Tonnage 1312 Built at Hull When built 1858
 By whom built — Owners J. Carlyle
 Port belonging to Birkenhead Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Green's Upper Dry Dock.

Last Survey, No. 7039 Port of Iron Classed A1.
 (S.S. No 1-68.)
4, 69.

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails Pivots

Breasthooks and Stems

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper Painted When put on —

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Good and efficient.

Good and

sufficient.

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Outside cleaned and painted, bottom coated with Penny's Composition.

Is now in good and efficient condition, and fit in my opinion to remain as classed - A1.

Committee's Minute 8th March 1870

J. H. Eastlake.

Character assigned

A1

Certificate (if required)

No. 765 Survey held at London Date 23rd Feb - 3rd March 1870
 on the Iron Ship "Star of Persia" Master J. W. Savage
 Tonnage 1227 Built at Belfast When built 1868
 By whom built Harland Owners Corry & Co.
 Port belonging to Belfast Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Wigram's Dry Dock

Last Survey, No. 6410 Port of Iron Classed A1.
D, 68.

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails Pivots

Breasthooks and Stems

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper Painted When put on 1868.

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Good and efficient.

Good and

sufficient.

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Outside cleaned and painted, bottom coated with Mc. Innes's Composition. Inside cleaned and painted from bilges up.

Is now in good and efficient condition, and fit in my opinion to remain as classed - A1.

Committee's Minute 8th March 1870

J. H. Eastlake.

Character assigned

A1

Certificate (if required)