

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 3105** Survey held at Glasgow Date Feb 18 1870
 on the Iron Ship "Dunfillan" Master Gamble
 Tonnage 853 built at Glasgow When built 1868
 By whom built Cutken & Mansel Owners W. Ross
 Port belonging to Glasgow Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Tod & M^cGregor's Slip

Last Survey, No. 6763 Port Iron. Classed A 1
 12, 68

REPAIRS

Now done, The bottom sighted, cleaned and painted -

Present Condition of the

Decks	} good	Greenails	} good	Windlass and Capstan	} good
Waterways		Breasthooks and Stemson		Pumps	
Comings	} firm	Transoms, Pointers, and Crutches	} efficient	Boats	} efficient
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} good	Ditto Ditto at other places	} where	Condition, how ascertained	} from the deck
Planksheers		Keelsons		Sails	
Sheerstrakes	} where	Clamps and Shelves	} seen	Anchors No. of <u>3 B. 15. 2 K.</u>	} good
Topsides		Ceiling		Cables	
Wales	} seen	Rudder	} sufficient	Hawsers and Warps	} sufficient
Blank (Bottom) and Counter		Copper Cement When put on <u>1868</u>		Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

She is now in good condition, fit in my opinion to remain as classed. A 1.

The Amount of Fee.....£ " : " : " is received by me,

Special..... " : " : "

Certificate (if required) " : " : "

Committee's Minute 15th March 1870

Character assigned A 1



© 2019

Lloyd's Register Foundation

IRON 446 - 0015