

15/3/70

7789

# ANNUAL SURVEYS.

Rev 16/3/70

No. 2226 Survey held at Liverpool. Date 28 Jan 23 Feb 18 70  
on the SHIP "NOR'WESTER" Master Burgess  
Tonnage 558 Built at N. Glasgow When built 1864 g. no.  
By whom built Hill Owners Jameson &  
Port belonging to Glasgow Destined Voyage Labrador Bay  
If Surveyed Afloat or in Dry Dock Canning Key etc. and afloat

Last Survey, No. 6934 Port of Iron. Classed A.S. 3. 69.  
(S.S. Nos. 69.)

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1864</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

Bottom cleaned and painted. Is now in good and efficient condition  
and in my opinion eligible to remain as classed.

Committee's Minute Liverpool 15<sup>th</sup> March 1870

Character assigned A 1

James Purdie.

Certificate (if required)

No. 2227 Survey held at Liverpool Date Feb. 10<sup>th</sup> to March 14<sup>th</sup> 18 70  
on the SHIP "Bedfordshire" Master J. Morgan  
Tonnage 1155 Built at L'pool When built 1863 g. no.  
By whom built Potter Owners Boulton & Co.  
Port belonging to L'pool Destined Voyage India  
If Surveyed Afloat or in Dry Dock Afloat & in Clarence Graving dock

Last Survey, No. 6910 Port of Iron. Classed A.S. 3.  
(S.S. Nos. 66) 369

The present Condition of the

Decks	Treenails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1863</u>	

Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Satisfactory

Bottom scraped & painted. Is now in an efficient condition  
& in my opinion eligible to remain as classed

Committee's Minute Liverpool 15<sup>th</sup> March 1870

Character assigned A 1

Edw. Wheeler

Certificate (if required)



"Nor' Wester"  
-22.226-  
"Bedfordshire"



© 2019

Lloyd's Register  
Foundation