

ANNUAL SURVEYS.

Rec 17/3/70

438 No. 3110 Survey held at Penfrew Date 3rd March 18 70
 on the A. Roslin Castle Master Alexander
 Tonnage 644 Built at Glasgow When built 1863 — 8 mo
 By whom built Connell Owners Shinner & Co
 Port belonging to Glasgow Destined Voyage Singapore
 If Surveyed Afloat or in Dry Dock Patent Slip

Last Survey, No. 6323 Port of Iron.

Classed A.1
S.S. No 1.66. — 6.68

The present Condition of the

Decks	Treenails <u>Rivets</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps <u>Do</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>Do</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. <u>Do</u>
Lower Deck Beams & Fastenings	Do Do at other places	Sails <u>Do</u>
Planksheers	Keelsons	Anchors No. of <u>Good</u>
Sheerstrakes	Clamps and Shelves	Cables <u>and</u>
Topsides	Ceiling	Hawsers and Warps <u>Sufficient</u>
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>✓</u> When put on	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen
Bottom cleaned, and painted with patent composition,
 This vessel is now in Good, and Efficient condition, and in my opinion
 eligible to remain as Classed,

Committee's Minute 18 March 18 70
 Character assigned A.1

Jm Moverly

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18 _____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18 _____
 Character assigned _____

© 2019
 Lloyd's Register
 Foundation
 Certificate (if required).