

# ANNUAL SURVEYS.

Survey held at London Date 28<sup>th</sup> Feb<sup>r</sup> - 15<sup>th</sup> March 1870  
 on the Iron Ship "Benton" Master H. E. Woollarton  
 Tonnage 952 Built at Newcastle When built 1864  
 By whom built Mars Hill Owners Barr & Co.  
 Port belonging to Liverpool Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Green's Upper Dry Dock.

Last Survey, No. 6928 Port of Iron Classed A1.  
 (S. S. No. 1-69.)  
 3, 69.

The present Condition of the

Decks  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings Good  
 Lower Deck Beams & Fastenings  
 Planksheers where  
 Sheerstrakes  
 Topsides seen.  
 Wales  
 Plank (Bottom) and Counter

Treenails Rivets  
 Breasthooks and Stemson  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the Openings Good  
 Ditto ditto at other places  
 Keelsons where  
 Clamps and Shells  
 Ceiling seen.  
 Rudder  
 Copper Cemented When put on 1864.

Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Sails  
 Anchors No. of Good and  
 Cables  
 Hawser and Warps sufficient.  
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Outside cleaned and painted, bottom coated with Kennedy's  
Composition.

Is now in good and efficient condition, and fit in my opinion  
to remain as classed - A1.

Committee's Minute 25<sup>th</sup> March 1870

J. H. Eastlake.

Character assigned A1

Certificate (if required)

No. 67 Survey held at London Date 11<sup>th</sup> Feb<sup>r</sup> - 21<sup>st</sup> March 1870  
 on the Iron Ship "Saint Marnock" Master J. Crawford  
 Tonnage 1258 Built at Liverpool When built 1867  
 By whom built Poyden Owners Paukin & Co.  
 Port belonging to Glasgow Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Thames Iron Works Dry Dock.

Last Survey, No. 7043 Port of Iron Classed A1.  
 5, 69.

The present Condition of the

Decks  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings Good  
 Lower Deck Beams & Fastenings  
 Planksheers where  
 Sheerstrakes  
 Topsides seen.  
 Wales  
 Plank (Bottom) and Counter

Treenails Rivets  
 Breasthooks and Stemson  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the Openings Good  
 Ditto ditto at other places  
 Keelsons where  
 Clamps and Shells  
 Ceiling seen.  
 Rudder  
 Copper Cemented When put on 1867.

Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Sails  
 Anchors No. of Good and  
 Cables  
 Hawser and Warps sufficient.  
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Outside cleaned and painted, also the hold throughout. Bottom  
tallowed.

Is now in good and efficient condition, and fit in my opinion to  
remain as classed - A1.

Committee's Minute 25<sup>th</sup> March 1870

J. H. Eastlake.

Character assigned A1

Certificate (if required).