

7042
ANNUAL SURVEYS.

No. 204 Survey held at Anchorage Date 1 April 1870
on the S.S. John Allen Master Macbeth
Tonnage 1188 Built at Charlestown When built 1865
By whom built Denton Owners Denton & Co
Port belonging to Charlestown Destined Voyage Buenos Ayres.
If Surveyed Afloat or in Dry Dock Dry dock

Last Survey, No. 6586 Port of Charlestown Classed 18 Shan Dec 10, 68 S.S. No. 1-68

The present Condition of the Ship is satisfactory

Decks <u>good</u>	Treenails <u>Pinch</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>6</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Composition</u> When put on <u>new</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways is good
Scraped and cleared the bottom up to lead which examined hulls,
ribs, keel plates, Rudder, and inside all fastenings found all in
good condition, painted with composition and recommended the vessel to
Committee's Minute 5 April 1870 the continuation of safe
Character assigned B Good Examiner Meyer

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the _____

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion, _____ Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____
Character assigned _____

Certificate (if required).

