

Iron. 78582
ANNUAL SURVEYS.

30796

1870

No. 346 Survey held at London Date April 5th 18 70
on the "S. Sea Queen" (Iron) Master Bunningham
Tonnage 873 Built at Glasgow When built 1858
By whom built Stephens Owners J. Allan & Co
Port belonging to London Destined Voyage Madras
If Surveyed Afloat or in Dry Dock Limetkiln & East India Docks

Last Survey, No. 7044 Port of Iron Classed A 1
(S.S. No 3.69) 4.69

The present Condition of the

Decks	Trunnions	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. <u>Good &</u>
Lower Deck Beams & Fastenings	Keelsons <u>Do Do</u> at other places <u>Good</u>	Sails <u>sufficient</u>
Planksheers <u>Good</u>	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good where seen

The bottom cleaned and painted.
This vessel is eligible in my opinion to remain as classed

Committee's Minute 19th April 18 70

Character assigned A 1

A 1
Thos. W. Wain

Certificate (if required)

No. 857 Survey held at London Date April 7th 18 70
on the "S. & Conflict" (Iron) Master G. Simons
Tonnage 1171 Built at Liverpool When built 1855
By whom built Liverpool Owners J. Smith Junr
Port belonging to Liverpool Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Limetkiln & East India Docks

Last Survey, No. 7089 Port of Iron Classed A 1 E.S. 68
5.69

The present Condition of the

Decks	Trunnions	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. <u>Good &</u>
Lower Deck Beams & Fastenings	Keelsons <u>Do Do</u> at other places <u>Good</u>	Sails <u>sufficient</u>
Planksheers <u>Good</u>	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good

The bottom cleaned and painted with two coats
of Zinc and one of Tallow.
This vessel is eligible to remain as
classed A 1

Committee's Minute 19th April 18 70

Character assigned A 1

Thos. W. Wain

Certificate (if required).