

ANNUAL SURVEYS.

No. 2228 Survey held at Birkenhead Date 19th April 1870
 on the Iron S. "Iron Queen" Master W. Larsson
 Tonnage 796 Built at Liverpool When built 1863-10 mo
 By whom built Potter Owners Girvin &
 Port belonging to Liverpool Destined Voyage Valparaiso
 If Surveyed Afloat or in Dry Dock Clovers dry dock

Last Survey, No. 6863 Port of Iron.

Classed A 1
 S.S. No. 1. 69 69

The present Condition of the

Decks	} <u>Good</u>	Ironails <u>Rivets</u>	} <u>Good</u>	Windlass and Capstan	} <u>Good</u>
Waterways		Breasthooks and Stems		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto ditto at other places	} <u>where</u>	Sails	} <u>and</u>
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Standing & Running Rigging	} <u>Suffr</u>
Plank (Bottom) and Counter		Copper <u>Cement</u> When put on <u>1863</u>			

General Observations and Opinion, Bottom cleaned and coated. Rudder pintles bushed
She is where seen in good condition and in my opinion
may remain as classed

Committee's Minute Liverpool 29th April 1870

Character assigned A 1

Will. C. Davey

Certificate (if required)

No. 576 Survey held at Birkenhead Date 23rd April 1870
 on the Iron S. "Merwanjee Saanjee" Master Bidwell
 Tonnage 1079 Built at Port Glasgow When built 1863-5 mo
 By whom built Reis Owners Johnston &
 Port belonging to Liverpool Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Claytons dry dock

Last Survey, No. 6571 Port of Iron.

Classed A 1
 S.S. No. 1. 66 68

The present Condition of the

Decks	} <u>Good</u>	Ironails <u>Rivets, a few new</u>	} <u>Good</u>	Windlass and Capstan	} <u>Good</u>
Waterways		Breasthooks and Stems		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto ditto at other places	} <u>where</u>	Sails	} <u>Suffr</u>
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter		Copper <u>Cement</u> When put on <u>1863</u>			

General Observations and Opinion, Bottom cleaned & coated. a few further rivets
taken out & renewed. She appears where seen in good condition
and in my opinion may remain as classed

Committee's Minute Liverpool 29th April 1870

Character assigned A 1

Will. C. Davey

Certificate (if required)

*"From Green
22281
"Merriam's Transcript"*



© 2019
Lloyd's Register
Foundation