

ANNUAL SURVEYS.

Rec 575770

No. 5766 Survey held at Greenock Date 25th April 1870
 743 on the Iron Ship Corlic Master A. Stevenson
 Tonnage 844 Built at Port Glasgow When built 1868 - 6 months
 By whom built R. Duncan & Co. Owners A. O. Leitch & Muir
 Port belonging to Greenock Destined Voyage Clyde to India
 If Surveyed Afloat or in Dry Dock In Dry Dock and Afloat

Last Survey, No. 5760 Port of Port Glasgow Classed A1
6282 Iron. (A.C.P.) 6/68

The present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Rivets Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do do</u>	Breasthooks and Stemson <u>do do</u>	Pumps <u>Good</u>
Comings <u>do do</u>	Transoms, Pointers, and Crutches <u>do do</u>	Boats <u>4 no. Good</u>
Upper Deck Beams & Fastenings <u>do & Firm</u>	Timbers of the Frame at the Openings <u>do do</u>	Masts, Yards, &c. <u>In good condition</u>
Lower Deck Beams & Fastenings <u>do & Firm</u>	Ditto ditto at other places <u>do do</u>	Sails <u>Two suits. good</u>
Planksheers <u>do do</u>	Keelsons <u>Good where seen</u>	Anchors No. of <u>3 B. 1 S. 2 K.</u>
Sheerstrakes <u>Plating do do</u>	Clamps and Shelves <u>do do</u>	Cables <u>Complete</u>
Topsides <u>do do do</u>	Ceiling <u>do do</u>	Hawsers and Warps <u>Well Found</u>
Wales <u>do do do</u>	Rudder <u>do do</u>	Standing & Running Rigging <u>In good order</u>
Plank (Bottom) and Counter <u>do do do</u>	Copper <u>Bottom coated</u> When put on <u>Now</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

In Dry Dock. Bottom cleaned and coated with two coats of McAlpine's Patent Paint and a coat of Patent Grease. - We are of opinion she is eligible to remain as classed

Committee's Minute 6th May 1870

Character assigned A1

Saml. Laphorn
A. J. S. & Co. Ltd.

Fee Paid £1.1.0
 Certificate (if required). May 1870

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion, _____
 Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____

Character assigned _____



© 2019

Lloyd's Register
 Certificate (if required).
 Foundation

IRON 446-0169