

ANNUAL SURVEYS.

No. 22332 Survey held at Liverpool Date April 22nd to 26th May 1870
 on the Barque "Romeo" Master J. W. Thomas
 Tonnage 641 Built at Liverpool When built 1869
 By whom built Royden Owners Bouring & Co
 Port belonging to Liverpool Destined Voyage Mellourn
 If Surveyed Afloat or in Dry Dock Brunswick Dry Dock & afloat

Last Survey, No. 6944 Port of Iron Classed A. 1
 69

The present Condition of the

Decks <u>Good</u>	Rivets <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Freenails <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Breasthooks and Stemson <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Sails <u>Good</u>
Planksheers <u>"</u>	Ditto ditto at other places <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Keelsons <u>"</u>	Cables <u>and</u>
Topsides <u>"</u>	Clamps and Shelves <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Ceiling <u>"</u>	Standing & Running Rigging <u>Sufficient</u>
Plank (Bottom) and Counter <u>"</u>	Rudder <u>"</u>	
	Copper <u>Cement</u> When put on <u>1869</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

The bottom scraped and coated with a composition.
 This Vessel when seen is in good condition, and in my opinion eligible to remain as classed A. 1

Committee's Minute Liverpool 10th June 1870

Character assigned A. 1

J. E. L.

J. Lawrence

Certificate (if required)

No. 7150 Survey held at Liverpool Date May 27th to June 4th 1870
 on the S. Ship "Sorata" Master Pastly
 Tonnage 786 Built at Liverpool When built 1869-4
 By whom built Bowdler Owners Walmley
 Port belonging to Liverpool Destined Voyage Valparaiso
 If Surveyed Afloat or in Dry Dock Brunswick Dry Dock & afloat

Last Survey, No. 7150 Port of Iron Classed A. 1
 6. 69.

The present Condition of the

Decks <u>Good where seen</u>	Rivets <u>Good</u>	Windlass and Capstan <u>Good where tested</u>
Waterways <u>"</u>	Freenails <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Breasthooks and Stemson <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Ditto ditto at other places <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Keelsons <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Clamps and Shelves <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Ceiling <u>"</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Rudder <u>"</u>	
	Copper <u>Cement</u> When put on <u>1869</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where tested

The bottom cleaned and painted with three coats of Davidson's composition.
 This Vessel is, when seen in good condition, and in my opinion eligible to remain as classed A. 1

Committee's Minute Liverpool 10th June 1870

Character assigned A. 1

J. E. L.

J. Lawrence

Certificate (if required).

Donata

Donne



© 2019

Lloyd's Register
Foundation