8060

ANNUAL SURVEYS.

Rec 27/6/70

in Reg. 866

No. 2068 Survey held at West Hartlepool Date 20th June 1870

on the Screw Steamer "Ludworth" Master Meldrum

Tonnage 440 304 Built at Glasgow When built 1866

By whom built Wingate Owners ~~Original Ludworth Steam Co. Limited~~

Port belonging to London Destined Voyage Coasting

If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 7510 Port of London. Classed ✠ A 1

The present Condition of the

Decks	~~Treenails~~ Rivets	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of 5 Bowers 1 Stream 2 Kedges
Sheerstrakes	Clamps and Shelfs	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
~~Plank~~ (Bottom) and Counter	~~Copper~~ When put on	

Good & Efficient, Where seen

Good & Efficient, Where seen

"Good & Efficient" "Good & Efficient" 63 One Anchor and Cable Tested to 15 Tons 12 Tons 3-0 Cable Tested to 15 Tons 12 Tons 3-0 W. Thomas & Son Hartlepool Surveyors

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good, Now coated with Paint & Black varnish.

Is now in a good & efficient state, fit for the safe conveyance of Dry & perishable goods to & from all parts of the World & may in my opinion remain as now classed ✠ A 1

Committee's Minute 28th June S.S. No. 4-69/18 70

Character assigned ✠ A 1

J. P. Glad Stone

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____

on the _____ Master _____

Tonnage _____ Built at _____ When built _____

By whom built _____ Owners _____

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelfs	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways

Minute _____ 18

ed _____

Certificate (if required).

IRON446-0304

© 2019 Lloyd's Register Foundation