

ANNUAL SURVEYS.

No. 53 Survey held at London Date 11th June 1870
 on the Iron Screw "Mercury" Master W. Hodge
 Tonnage 727⁸³⁹ Built at Newcastle When built 1864
 By whom built Palmer Owners Palmer & Co.
 Port belonging to Newcastle Destined Voyage Syue & then to Cronstadt
 If Surveyed Afloat or in Dry Dock Victoria Pontoons.

Last Survey, No. 7205 Port of Iron. Classed AB 1.
 (S. S. No. 2-69.)
 5, 69.

The present Condition of the

Decks	<u>Good</u> <u>where</u> <u>seen.</u>	Treenails <u>Rivets</u>	<u>Good</u> <u>where</u> <u>seen.</u>	Windlass and Capstan	<u>Good and</u> <u>complete</u> <u>where seen.</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shells		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper Cemented When put on <u>1864</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Outside cleaned and painted, and bottom tallowed.
Is now in good and efficient condition, and fit in my
opinion to remain as classed - AB 1. J. H. Eastlake,

Committee's Minute 1st July 1870

Character assigned AB 1

Certificate (if required).

No. 43 Survey held at London Date 27th June 1870
 on the Iron Screw "Garrison" Master W. Gunn
 Tonnage 702⁵³⁰ Built at Glasgow When built 1867
 By whom built Aiken Owners Laing & Co. Ltd.
 Port belonging to Leith Destined Voyage Syue & then to Archangel
 If Surveyed Afloat or in Dry Dock Victoria Pontoons.

Last Survey, No. 6060 Port of Iron. Classed AB 1.
 2, 68.

The present Condition of the

Decks	<u>Good</u> <u>where</u> <u>seen.</u>	Treenails <u>Rivets</u>	<u>Good</u> <u>where</u> <u>seen.</u>	Windlass and Capstan	<u>Good and</u> <u>complete</u> <u>where seen.</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shells		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper Cemented When put on <u>1867</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

The owner preferred to run another voyage before
going through the No 1 P. Survey. Outside cleaned, bottom black
varnished, topsides painted.
Is now in good and efficient condition, and fit in my
opinion to remain as classed
- AB 1. J. H. Eastlake,

Committee's Minute 1st July 1870

Character assigned AB 1

Certificate (if required).