

ANNUAL SURVEYS.

293 No. 103 Survey held at London Date 1st June - 2nd July 18 70
 on the Iron Ship "Portland" Master Coster
 Tonnage 872 Built at P. Glasgow When built 1862
 By whom built Reid Owners Temperley &
 Port belonging to London Destined Voyage Shanghai
 If Surveyed Afloat or in Dry Dock Fletcher's Dry Dock.

Last Survey, No. 6756 Port of Iron.

Classed A1.
 (S. S. No. 2-68.)
 11, 68.

The present Condition of the

Decks	} <u>Good</u>	Treenails <u>Rivets</u>	} <u>Good</u>	Windlass and Capstan	} <u>Good and</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		<u>Ditto</u> ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		<u>Clamps and Shells</u>		Cables	
Topsides	} <u>sun.</u>	Ceiling	} <u>where sun.</u>	Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper <u>Cemented</u> When put on <u>1/6 3.</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Outside cleaned and painted, and bottom tallowed. New Rudder, Braces.
Is now in good and efficient condition, and fit in my opinion to remain as classed - A1.

J. H. Eastlake.

Committee's Minute 12th July 18 70

Character assigned A1

Certificate (if required).

157 No. 103 Survey held at London Date 22nd June - 2nd July 18 70
 on the Iron Ship "Jane Porter" Master A. Wilson
 Tonnage 953 Built at Belfast When built 1860
 By whom built Harland Owners Corry & S^{rs}
 Port belonging to Belfast Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Wigrams Dry Dock.

Last Survey, No. 7449 Port of Iron.

Classed A1.
 (S. S. No. 2-68.)
 10, 69.

The present Condition of the

Decks	} <u>Good</u>	Treenails <u>Rivets</u>	} <u>Good</u>	Windlass and Capstan	} <u>Good and</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		<u>Ditto</u> ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		<u>Clamps and Shells</u>		Cables	
Topsides	} <u>sun.</u>	Ceiling	} <u>where sun.</u>	Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper <u>Cemented</u> When put on <u>3</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Inside cleaned and painted from bilges up. Outside cleaned and painted, bottom coated with Mr. Innes's Composition.
Is now in good and efficient condition, and fit in my opinion to remain as classed - A1.

Committee's Minute 12th July 18 70

Character assigned A1

J. H. Eastlake.

Certificate (if required).