

ANNUAL SURVEYS.

30950
Rev 2/1/70

No. 46 Survey held at London Date 13 June - 1st July 18 70
on the Iron Ship "Santallon Castle" Master J. Brown
Tonnage 105-7 Built at Grunoek When built 1865
By whom built Stiele Owners Currie & Co.
Port belonging to Liverpool Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Wigram's Dry Dock.

Last Survey, No. 7476 Port of Iron. Classed A1.
(S.S. No 1-69.)
10, 69.

The present Condition of the

Decks	} <u>Good</u> <u>where</u> <u>seen.</u>	Treenails <u>Rivets</u>	} <u>Good</u> <u>where</u> <u>seen.</u>	Windlass and Capstan	} <u>Good and</u> <u>complete</u> <u>where seen.</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides	Ceiling	Hawsers and Warps	} <u>where seen.</u>		
Wales	Rudder	Standing & Running Rigging			
Planks (Bottom) and Counter		Copper <u>Cemented</u> When put on <u>1865</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Outside cleaned and painted, bottom coated with Mc. Innes's Composition.

Is now in good and efficient condition, and fit in my opinion to remain as classed - A1.

J. H. Eastlake,

Committee's Minute 5th July 18 70

Character assigned *A1 MA

Certificate (if required).

No. 665 Survey held at London Date 27 June - 1st July 18 70
on the Iron Ship "Stirling Castle" Master J. H. Hamilton
Tonnage 1165 Built at Glasgow When built 1863
By whom built Napier Owners Currie & Co.
Port belonging to Liverpool Destined Voyage New York
If Surveyed Afloat or in Dry Dock Wigram's Dry Dock

Last Survey, No. 7244 Port of Iron. Classed A1.
(S.S. No 1-66.) - 11 mo.
7, 69.

The present Condition of the

Decks	} <u>Good</u> <u>where</u> <u>seen.</u>	Treenails <u>Rivets</u>	} <u>Good</u> <u>where</u> <u>seen.</u>	Windlass and Capstan	} <u>Good and</u> <u>complete</u> <u>where seen.</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides	Ceiling	Hawsers and Warps	} <u>where seen.</u>		
Wales	Rudder	Standing & Running Rigging			
Planks (Bottom) and Counter		Copper <u>Cemented</u> When put on <u>1865</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Outside cleaned and painted, bottom coated with Mc. Innes's Composition.

Is now in good and efficient condition; fit in my opinion to remain as classed - A1.

J. H. Eastlake,

Committee's Minute 5th July 18 70

Character assigned *A1 MA

Certificate (if required).