

ANNUAL SURVEYS.

No. 160 Survey held at London Date 20th June July 8 1870
 on the Iron Ship Berar Master J. H. Hillman
 Tonnage 902 Built at Sunderland When built 1863.
 By whom built Pile Owners J. D. Tyser
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Raschliff Croft dry dock & East India Dock

Last Survey, No. 7161

Port of Iron

Classed A. 1, S. S. No 1/58
69

The present Condition of the

	<u>good</u>	<u>Greenails</u>	<u>Rivets</u>	<u>good</u>	
Decks	<u>good</u>				Windlass and Capstan <u>in good order</u>
Waterways	<u>✓</u>	Breasthooks and Stemson	<u>✓</u>		Pumps <u>✓</u>
Comings	<u>✓</u>	Transoms, Pointers, and Crutches	<u>✓</u>		Boats <u>✓</u>
Upper Deck Beams & Fastenings	<u>✓</u>	Timbers of the Frame at the Openings	<u>✓</u>		Masts, Yards, &c. <u>✓</u>
Lower Deck Beams & Fastenings	<u>✓</u>	Ditto ditto at other places	<u>✓</u>		Sails <u>✓</u>
Planksheers	<u>✓</u>	Keelsons	<u>✓</u>		Anchors No. of <u>3 & 1 S, 2 K,</u> <u>✓</u>
Sheerstrakes	<u>✓</u>	Clamps and Shelves	<u>✓</u>		Cables <u>✓</u>
Topsides	<u>✓</u>	Ceiling	<u>✓</u>		Hawsers and Warps <u>✓</u>
Wales	<u>✓</u>	Rudder <u>efficient</u>	<u>✓</u>		Standing & Running Rigging <u>✓</u>
Plank (Bottom) and Counter	<u>✓</u>	Copper	When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good

Clean'd and recoased the bottom.

As far as seen she appears to be in good condition

and is in my opinion enabled to remain
as class'd

Committee's Minute

15th July 1870

Character assigned

A. 1

Certificate (if required)

120N446-0363

Brown
Glenwith



© 2019

Lloyd's Register
Foundation