

No.

Survey held at

London

Date 27th June - 15th July 1870

on the

Iron S. "Langstone"

Master

W. S. Turnbull

Tonnage

746

Built at

Sunderland

When built

1869

By whom built

Pile

Owners

H. Ellis

Port belonging to

London

Destined Voyage

Colombo

If Surveyed Afloat or in Dry Dock

Victoria Pontoons

Last Survey, No.

7195

Port of

Ad.

Classed

A1

6, 69.

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper Cemented When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good where examined.

Outside cleaned and painted, and bottom tallowed. Inside cleaned and painted from bilges up.

Is now in good and efficient condition, and fit in my opinion to remain as classed - # A1.

Committee's Minute

22nd July

1870

Character assigned

J. H. Eastlake.

Certificate (if required).

IRON 446-0400