

# ANNUAL SURVEYS.

Supp<sup>r</sup> No. 8220 Survey held at London Date 9<sup>th</sup> - 14<sup>th</sup> July 1870  
 on the Iron Sew "Mid Surrey" Master E. Harwey  
 Tonnage 855 Built at Newcastle When built 1870  
 By whom built Palmer Owners Dixon & Co.  
 Port belonging to London Destined Voyage Sea of Azov  
 If Surveyed Afloat or in Dry Dock Afloat - Millwall Docks.

Last Survey, No. 8157 Port of Iron Classed 90 A1  
6, 70.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Visited the vessel at the request of the owner for the purpose of recommending a method for making one of the hold beams and two pieces of the angle iron ties moveable in the event of it being required.

J. H. Eastlake;

Committee's Minute 26<sup>th</sup> August 1870

Character assigned As before

Certificate (if required).

878 No. 878 Survey held at London Date 11<sup>th</sup> August 1870  
 on the Iron Sew "Avebury" Master J. Potts  
 Tonnage 697 Built at Middlesborough When built 1869  
 By whom built Backhouse Owners P. Hudson  
 Port belonging to Sunderland Destined Voyage Frieste  
 If Surveyed Afloat or in Dry Dock Reed's Dry Dock.

Last Survey, No. 77423 Port of Iron Classed A1. not  
2, 70

The present Condition of the

Decks	Treenails <u>Planks</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper Cemented When put on <u>1869</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Outside cleaned and coated - bottom with black varnish. Is now in good and efficient condition, and fit in my opinion to remain as classed - A1.

Committee's Minute 26<sup>th</sup> August 1870

Character assigned As before

J. H. Eastlake;

Certificate (if required).

IRON447-0020