

# ANNUAL SURVEYS.

No. 60m  
Register  
Book

No. 2006 Survey held at West Hartlepool Date 3<sup>rd</sup> October 1850  
on the Iron Screw Steamer "Gazelle" Master \_\_\_\_\_  
Tonnage 563 Built at Hartlepool When built 1869  
By whom built Withy Owners W. & A. G. G.  
Port belonging to West Hartlepool Destined Voyage Baltic  
If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 7379 Port of Iron Classed A1

The present Condition of the

|                               |                                  |                            |
|-------------------------------|----------------------------------|----------------------------|
| Decks                         | Treenails <u>Rivets</u>          | Windlass and Capstan       |
| Waterways                     | Breasthooks and Stemson          | Pumps                      |
| Comings                       | Transoms, Pointers, and Crutches | Boats                      |
| Upper Deck Beams & Fastenings | Timbers of the Frame             | Masts, Yards, &c.          |
| Lower Deck Beams & Fastenings | Keelsons                         | Sails                      |
| Planksheers                   | Clamps and Shelves               | Anchors No. of             |
| Sheerstrakes                  | Ceiling                          | Cables                     |
| Topsides                      | Rudder                           | Hawsers and Warps          |
| Wales                         | Copper                           | Standing & Running Rigging |
| Plank (Bottom) and Counter    | When put on                      |                            |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

*Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion remain as now classed A1*

Committee's Minute up to October 18

Character assigned A1

Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 185 \_\_\_\_\_  
on the \_\_\_\_\_ Master \_\_\_\_\_  
Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

|                               |                                  |                            |
|-------------------------------|----------------------------------|----------------------------|
| Decks                         | Treenails                        | Windlass and Capstan       |
| Waterways                     | Breasthooks and Stemson          | Pumps                      |
| Comings                       | Transoms, Pointers, and Crutches | Boats                      |
| Upper Deck Beams & Fastenings | Timbers of the Frame             | Masts, Yards, &c.          |
| Lower Deck Beams & Fastenings | Keelsons                         | Sails                      |
| Planksheers                   | Clamps and Shelves               | Anchors No. of             |
| Sheerstrakes                  | Ceiling                          | Cables                     |
| Topsides                      | Rudder                           | Hawsers and Warps          |
| Wales                         | Copper                           | Standing & Running Rigging |
| Plank (Bottom) and Counter    | When put on                      |                            |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute \_\_\_\_\_ 18

Character assigned \_\_\_\_\_



© 2019

Certificate (if required).

IRON 447-0141