

ANNUAL SURVEYS.

3/153

No. Survey held at London Date 21st - 31st Sep^r 1870
 on the St'm. (Iron) "Harwich" Master H. Lawrence
 Tonnage 73-0 Built at London When built 1864
 By whom built Simpson Owners Gt East. Rail'y Co.
 Port belonging to London Destined Voyage Harwich & then Antwerp
 If Surveyed Afloat or in Dry Dock Reed's Dry Dock.

Last Survey, No. 6699 Port of Iron Classed A1.
(S.S. No. 1-68.)
10, 68.

The present Condition of the

Decks	} <u>Good</u>	Treenails / Rivets	} <u>Good</u>	Windlass and Capstan	} <u>Good and</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto ditto at other places	} <u>where</u>	Sails	} <u>complete</u>
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen.</u>	Rudder	} <u>seen.</u>	Standing & Running Rigging	} <u>seen.</u>
Plank (Bottom) and Counter		Copper <u>Cemented</u> When put on <u>1/64.</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Outside cleaned and painted: bottom coated with
Peacock's Composition.
Is now in good and efficient condition, and fit
in my opinion to remain as classed - A1.

Committee's Minute

7th October 1870

Character assigned

A1

J. H. Eastlake.

Certificate (if required).

No. Survey held at London Date 3rd October 1870
 on the Iron Ste "Princess" Master H. Snow
 Tonnage 1160 Built at Hull When built 1869
 By whom built Humphreys Owners Gee & Co.
 Port belonging to Hull Destined Voyage Friestli
 If Surveyed Afloat or in Dry Dock Reed's Dry Dock.

Last Survey, No. 7874 Port of Iron Classed A1 without
4, 70.

The present Condition of the

Decks	} <u>Good</u>	Treenails / Rivets	} <u>Good</u>	Windlass and Capstan	} <u>Good and</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto ditto at other places	} <u>where</u>	Sails	} <u>complete</u>
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen.</u>	Rudder	} <u>seen.</u>	Standing & Running Rigging	} <u>seen.</u>
Plank (Bottom) and Counter		Copper <u>Cemented</u> When put on <u>1/69.</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Topsides cleaned and painted: bottom cleaned and
coated with coal-tar and black-lead.
Is now in good and efficient condition, and fit in my
opinion to remain as classed - A1.

Committee's Minute

7th October 1870

Character assigned

A1

J. H. Eastlake.

Certificate (if required).

IRON 447 - 0144