

ANNUAL SURVEYS.

No. 2252 Survey held at Liverpool Date October 5th 1870
 on the S.S. "Nagpore" Master J. J. Grevellick
 Tonnage 1198 Built at Glasgow When built 1863-9 M.
 By whom built Barclay Owners W. Rome
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Brunswick Dry Dock & Afloat

Last Survey, No. 5918 Port of Iron. Classified * A. 1
L. S. N. 1. 67. 9

The present Condition of the

Decks	<u>Good</u>	Rivets	<u>When seen good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Freenails	"	Pumps	"
Comings	"	Breasthooks and Stems	"	Boats	<u>Four</u>
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Sails	"
Planksheers	"	Ditto ditto at other places	"	Anchors No. of	<u>3 B. 1 S. 2 H.</u>
Sheerstrakes	"	Keelsons	"	Cables	<u>Good</u>
Topsides	"	Clamps and Shelves	"	Hawsers and Warps	<u>Good</u>
Wales	"	Ceiling	"	Standing & Running Rigging	<u>Sufficient</u>
Plate	"	Rudder	"		
Blank (Bottom) and Counter	"	Copper	<u>Cement</u> When put on <u>1863</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

The Bottom cleaned and painted, refitted the upper brace of rudder, fitted new jibboom of P. Pine. This vessel is now in good condition when seen, and in my opinion eligible to remain

Committee's Minute Liverpool 18th October 1870 as classed.

Character assigned

* A. 1

J. Lawrence

Certificate (if required)

No. 628 Survey held at Liverpool Date 29th Oct 1870
 on the S.S. "Annie Story" Master J. Penny
 Tonnage 591 Built at Glasgow When built 1867-2 M.
 By whom built Stephen Owners R. G. Sharp
 Port belonging to Liverpool Destined Voyage Lima
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock

Last Survey, No. 5335 Port of Iron. Classified * A. 1
2. 67

The present Condition of the

Decks	<u>Good</u>	Rivets	<u>When seen good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Freenails	"	Pumps	"
Comings	"	Breasthooks and Stems	"	Boats	<u>Four</u>
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches	"	Masts, Yards, &c.	<u>Iron deck</u>
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Sails	"
Planksheers	"	Ditto ditto at other places	"	Anchors No. of	"
Sheerstrakes	"	Keelsons	"	Cables	<u>Sufficient</u>
Topsides	"	Clamps and Shelves	"	Hawsers and Warps	"
Wales	"	Ceiling	"	Standing & Running Rigging	"
Plate	"	Rudder	"		
Blank (Bottom) and Counter	"	Copper	<u>Cement</u> When put on <u>1867</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good

The Bottom cleaned and coated with Davison's composition. She is now in good condition and in my opinion eligible to remain as classed

Committee's Minute Liverpool 18th October 1870

Character assigned

* A. 1

J. Lawrence

Certificate (if required).

IRON 447-0166

"Nagpore"

"Annie Story" 22502



© 2019

Lloyd's Register
Foundation