

IRON 447-0187

8383

27/183

## ANNUAL SURVEYS.

No. 229 Survey held at London Date Feb<sup>r</sup> 30<sup>th</sup> 1870  
 on the Iron Screw Steamer Trevethick Master G. Carr  
 Tonnage 767 Built at Newcastle When built 1866  
 By whom built 594 Palmer & Co<sup>y</sup> Owners Hutchinson  
 Port belonging to Newcastle Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No.

7749

Port of

Iron.

Classed

A. 1 S.S. no 1 /68.  
2.70

The present Condition of the

| Decks                         | <u>good</u> | Treenails                            | <u>Rivets</u> | <u>good</u>        | Windlass and Capstan                         | <u>in good order</u> |
|-------------------------------|-------------|--------------------------------------|---------------|--------------------|--|----------------------|
| Waterways                     | <u>1</u>    | Breasthooks and Stemson              | <u>1</u>      | <u>1</u>           | Pumps  | <u>1</u>             |
| Comings                       | <u>1</u>    | Transoms, Pointers, and Crutches     | <u>1</u>      | <u>1</u>           | Boats  | <u>1</u>             |
| Upper Deck Beams & Fastenings | <u>1</u>    | Timbers of the Frame at the Openings | <u>1</u>      | <u>1</u>           | Masts, Yards, &c.                            | <u>1</u>             |
| Lower Deck Beams & Fastenings | <u>1</u>    | Ditto ditto at other places          | <u>1</u>      | <u>1</u>           | Sails  | <u>1</u>             |
| Planksheers                   | <u>1</u>    | Keelsons                             | <u>1</u>      | <u>1</u>           | Anchors No. of <u>3 &amp; 18, 2 &amp; 18</u> | <u>1</u>             |
| Sheerstrakes                  | <u>1</u>    | Clamps and Shelves                   | <u>1</u>      | <u>1</u>           | Cables                                       | <u>1</u>             |
| Topsides                      | <u>1</u>    | Ceiling                              | <u>1</u>      | <u>1</u>           | Hawsers and Warps                            | <u>1</u>             |
| Wales                         | <u>1</u>    | Rudder <u>efficient</u>              | <u>1</u>      | <u>1</u>           | Standing & Running Rigging                   | <u>1</u>             |
| Plank (Bottom) and Counter    | <u>1</u>    | Copper                               | <u>1</u>      | <u>When put on</u> |  |                      |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Overhauled the bottom, caulked busses found in midships (found strained a trifle.) She is as far as seen in good condition, and is in my opinion entitled to remain as classed to Samuel Menon.

Committee's Minute

25<sup>th</sup> October 1870

Character assigned

A 1

Certificate (if required).



Wendell  
Bradshaw



© 2019

Lloyd's Register  
Foundation