

## REPORT of SURVEY for REPAIRS.

No. in  
Reg. Book.  
46

No. 2092

Survey held at West Hartlepool Date, first Survey 26<sup>th</sup> Oct. Last Survey 20<sup>th</sup> Oct. 1870

on the

Screw Steamer "Magdala"

Master

Thos. Robinson

Tonnage

677 + 452 built at

Hartlepool

When built

1870

By whom built

Withy

Owners

Appleby &amp; Co.

Port belonging to

West Hartlepool

Destined Voyage

Baltic

If Surveyed Afloat or in Dry Dock

In Dry Dock

Last Survey, No.

7906

Port

Iron

Classed

A 1

REPAIRS, &amp;c.

This vessel took the War on leaving <sup>Hartlepool</sup> ~~this~~ Harbour laden with coals. A few butts & edges of shell plating shaken, now caulked up. Two warps renewed. Bottom cleaned down & coated with black barnish, paint & black lead.

## Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &amp;c.

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Caulking of

Bottom, Deck, &amp; Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing &amp; Running Rigging

Cargo and Main Hatchways

Hatches

Is now in a good & efficient state, fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion remain as now classed A 1

The Amount of Entry Fee..... £ - : - : - is received by me,

Damage Survey

Special.....

Oct 1870

Certificate (if required)

Committee's Minute

1<sup>st</sup> November 1870

Character assigned

A 1



© 2019

Lloyd's Register  
Foundation

IRON 447-0192