

ANNUAL SURVEYS.

No. 22515 Survey held at Liverpool Date Oct 8th 1870
 on the Iron Ship Iron Duke Master J. Parry
 Tonnage 1435 Built at Liverpool When built 1863-3rd
 By whom built Lawrence Owners Harford & Co
 Port belonging to Liverpool Destined Voyage Calcutta.
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock and afloat.

Last Survey, No. 6701 Port of Iron.

Classed

*A1.

The present Condition of the

Decks good
 Waterways "
 Comings "
 Upper Deck Beams & Fastenings Iron
 Lower Deck Beams & Fastenings good
 Planksheers where
 Sheerstrakes seen
 Topsides
 Wales
 Plank (Bottom) and Counter Painted.

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings Iron
 Ditto ditto at other places good
 Keelsons where
 Clamps and Shelves seen
 Ceiling
 Rudder
 Copper Cement When put on 1863

Windlass and Capstan good
 Pumps "
 Boats good and Complete.
 Masts, Yards, &c. "
 Sails good and Complete.
 Anchors No. of 3 B. 1 S. 2 P.
 Cables good where seen.
 Hawkers and Warps good
 Standing & Running Rigging good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good.
 This vessel is now in good Condition and in my opinion eligible to remain as Classed *A1.

Committee's Minute Liverpool 4th November 1870

Character assigned *A1

J. F. Light.

Certificate (if required)

No. 206 Survey held at Liverpool Date Oct 15th 1870
 on the Iron Ship Thunderbolt Master Goldsmoor
 Tonnage 1193 Built at Hull When built 1863-8th
 By whom built Samuelson Owners Coupland & B^{rs}
 Port belonging to Liverpool Destined Voyage McLbourne.
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock and afloat.

Last Survey, No. 6557 Port of Iron.

Classed

*A1.

The present Condition of the

Decks good
 Waterways "
 Comings "
 Upper Deck Beams & Fastenings Iron
 Lower Deck Beams & Fastenings good
 Planksheers where
 Sheerstrakes seen
 Topsides
 Wales
 Plank (Bottom) and Counter Painted

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings Iron
 Ditto ditto at other places good
 Keelsons where
 Clamps and Shelves seen
 Ceiling
 Rudder
 Copper Cement When put on 1863

Windlass and Capstan good
 Pumps "
 Boats good and Sufficient
 Masts, Yards, &c. "
 Sails good and Complete.
 Anchors No. of 3 B. 1 S. 2 P.
 Cables good where seen.
 Hawkers and Warps good
 Standing & Running Rigging good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good.
 This vessel is now in good Condition and in my opinion eligible to remain as Classed *A1.

Committee's Minute Liverpool 4th November 1870

Character assigned *A1

J. F. Light.

Certificate (if required).

IRON 447-0222

Iron Duke
22.515
"Thunderbolt"



© 2019

Lloyd's Register
Foundation