

# ANNUAL SURVEYS.

8421 31213

54 No. Survey held at London Date 1st Nov 1870  
 on the iron bark "Dulwich the South" Master Stephen Jas Adair  
 Tonnage 375 Built at Switzerland When built 1864 - 11 mo  
 By whom built Pile Owners H. Ellis R. R. Grant  
 Port belonging to Glasgow ~~London~~ Destined Voyage not fixed per Register  
 If Surveyed Afloat or in Dry Dock London patent ship and Afloat Spain River

Last Survey, No. 7475 Port of Iron. Classed SAI  
1st Nov 69 10.69

The present Condition of the

Decks	Transoms <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Iron</u> When put on <u>1864</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where examined  
Bottom cleaned and coated with paint and yellow  
is now in good and efficient condition, and in our opinion  
eligible to remain as classed.  
 Committee's Minute 8th November 1870  
 Character assigned \* A 1 W. Turner

Certificate (if required)

258 No. Survey held at London Date 1st Nov 1870  
 on the iron bark "William Wilson" Master J. Phillips  
 Tonnage 312 Built at Pistol When built 1863 - 8 mo  
 By whom built Hyde Owners J. Davidson  
 Port belonging to Whitehaven Destined Voyage not fixed  
 If Surveyed Afloat or in Dry Dock Duke Shore Dry Dock and Afloat

Last Survey, No. 6279 Port of Iron. Classed BAI  
1st Nov 68 4.68

The present Condition of the

Decks	Transoms <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where examined  
Bottom cleaned and painted  
is now in good and efficient condition  
and in our opinion eligible to remain as classed.  
 Committee's Minute 8th November 1870  
 Character assigned 13 A 1 W. Turner

Certificate (if required).

IRON 447-0227