

ANNUAL SURVEYS.

No. 261 Survey held at London Date 2nd Nov^r 1870
 on the iron ship "Jessie Readman" Master Strachan
 Tonnage 962 Built at Greenock When built 1869-11 mo
 By whom built Scott Owners Albion Shipping Company
 Port belonging to Glasgow Destined Voyage Stago
 If Surveyed Afloat or in Dry Dock North Dock Dry Dock

Last Survey, No. 7591 Port of Iron Classed Fall
11.69.

The present Condition of the

Decks	Transoms <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems <u>Good where Examined</u>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>1 cm</u> When put on <u>1869</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where Examined
Bottom cleaned and coated with Red Lead and patent Compound
Is now in good and efficient condition, and in my
opinion eligible to remain as classed.
 Committee's Minute 11th November 1870
 Character assigned * A 1 W.H.

Certificate (if required)

No. 803 Survey held at London Date 2nd Nov^r 1870
 on the iron bark "Asterion" Master D. Stupland
 Tonnage 509 Built at Linzerland When built 1869-1 mo
 By whom built Slip Owners R. Penley
 Port belonging to Shoreham Destined Voyage East India
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock

Last Survey, No. 7535 Port of Iron Classed Fall
11.69

The present Condition of the

Decks	Transoms <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems <u>Good where Examined</u>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>1 cm</u> When put on <u>1869</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where Examined
Bottom cleaned and coated with Paint and Sallow.
Is now in good and efficient condition and in my
opinion eligible to remain as classed.
 Committee's Minute 11th November 1870
 Character assigned * A 1 W.H.

Certificate (if required).