

ANNUAL SURVEYS.

No. 22544 Survey held at Liverpool Date 17 October 21 October 1870
 on the BARQUE "PACIFIC" Master Nadriel
 Tonnage 429 Built at Glasgow When built 1867. 3. mo
 By whom built Stephen Owners Steuellon & Co
 Port belonging to Sirassu Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Canning Key Rock and afloat.

Last Survey, No. 6935 Port of Iron.

Classed * A. 1.

2. 69.

The present Condition of the

Decks	Greenails <u>Roofs</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1867.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

Bottom scraped and painted. She is now in good condition - and in my opinion is eligible to remain as classed.

Committee's Minute Liverpool 18th November 1870

Character assigned A. 1.

Certificate (if required)

No. 46 Survey held at Liverpool Date 24 Oct. to 9 November 1870
 on the SF. "JAMES DUCKETT" Master Naylor
 Tonnage 231 Built at Bryda When built 1864. 12. mo
 By whom built Green & Co Owners Dockett & Co
 Port belonging to Preston Destined Voyage Lagos.
 If Surveyed Afloat or in Dry Dock Canning Key Rock and afloat.

Last Survey, No. 7036 Port of Iron.

Classed B. 1.

B. S. No 1-187 7. 68.

The present Condition of the

Decks	Greenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1864</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

Bottom scraped and painted. She is now in good condition - and in my opinion is eligible to remain as classed.

Committee's Minute Liverpool 18th November 1870

Character assigned B. 1.

Certificate (if required).

IRON 447-0269

"Pacific"
4

James Duckett
22544



© 2019

Lloyd's Register
Foundation