

REPORT of SURVEY for REPAIRS.

8483

31246

No. in Reg. Book. 198 No. 1097 Survey held at London Date, first Survey 1st Nov. Last Survey Nov. 3rd 1870
 on the Ship Sarah & Emma Master C. Roberts
 Tonnage 1097 built at Liverpool When built 1860 ^{9th Mth}
 By whom built Vernon Owners Hughes & Comp^y
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Pontoon.
Change of Owners.
 Last Survey, No. 8209 Port Am. Classed *A. 1. S.S. No 2/69
8.70

REPAIRS, &c.

*Cleaned and recoated the bottom,
 and overhauled her as far as practicable
 inside and outside.*

Present Condition of the

Decks	<i>good</i>	Freenails	<i>Rivets where seen</i>	<i>good</i>	Windlass and Capstan	<i>in good order</i>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	<i>from the deck</i>
Plank sheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of	<i>3 & 1 S. 2 H.</i>
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	<i>efficient</i>	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<i>When put on</i>	"	Standing & Running Rigging	"
Engine Room Skylights	"	Caulking of	<i>good</i>	"		
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways	<i>good</i>	"		
General Observations and Opinion,		Scuppers	<i>good</i>	"	Cargo and Main Hatchways	<i>good</i>
		Hatches	<i>good</i>	"		

*She appears to be in good condition and I am
 of opinion she is entitled to remain as classed
 A. 1.
 Samuel Persons*

The Amount of Entry Fee..... £ / : : is received by me,

Special..... 1 : 1 : :

Certificate (if required) : 5 : :

Committee's Minute 29th Nov 1870

Character assigned *A 1



© 2019

Lloyd's Register
 Foundation

IRON 447-0291