

# ANNUAL SURVEYS.

No. 2239 Survey held at Liverpool Date 17<sup>th</sup> to 10 November 1870  
 on the BARQUE GLENCOWN Master Path  
 Tonnage 426 Built at Glasgow When built 1863 1 mo  
 By whom built Stephen Owners Newitt & Co  
 Port belonging to Whitehaven Destined Voyage Sinal  
 If Surveyed Afloat or in Dry Dock Canning Key block afloat.

Last Survey, No. 6037 Port of Iron. Classed \*A  
 Present Condition of the See 1. 67 2. 68

ways	Treenails <u>Rocks.</u>	Windlass and Capstan
gs	Breasthooks and Stemson	Pumps
Deck Beams & Fastenings	Transoms, Pointers, and Crutches	Boats
Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
sheers	Ditto ditto at other places	Sails
trakes	Keelsons	Anchors No. of
les	Clamps and Shelves	Cables
(Bottom) and Counter	Ceiling	Hawsers and Warps
	Rudder	Standing & Running Rigging
	Copper <u>Cement</u> When put on <u>1863</u>	

al Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

Bottom scraped and painted - she is now in good condition  
and in my opinion is eligible to remain as classed.

Committee's Minute Liverpool 23<sup>rd</sup> December 1870 James Indie.  
 Character assigned \*A

Certificate (if required)

No. 112 Survey held at Liverpool Date 28 Oct 16 December 1870  
 on the BARQUE SAN LORENZO Master Neutrecht  
 Tonnage 480 Built at Liverpool When built 1861 7 mo  
 By whom built Lones Owners Broomhall  
 Port belonging to Liverpool Destined Voyage Calparaiso  
 If Surveyed Afloat or in Dry Dock Canning Key block afloat.

Last Survey, No. 7615 Port of Iron. Classed \*A  
 Present Condition of the See 2. 69 12. 69

ways	Treenails <u>Rocks.</u>	Windlass and Capstan
ings	Breasthooks and Stemson	Pumps
er Deck Beams & Fastenings	Transoms, Pointers, and Crutches	Boats
er Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
ksheers	Ditto ditto at other places	Sails
strakes	Keelsons	Anchors No. of
les	Clamps and Shelves	Cables
s	Ceiling	Hawsers and Warps
k (Bottom) and Counter	Rudder	Standing & Running Rigging
	Copper <u>Cement</u> When put on <u>64</u>	

al Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Bottom scraped and painted. she is now in good condition.  
and in my opinion is eligible to remain as classed.

Committee's Minute Liverpool 23<sup>rd</sup> December 1870 James Indie.  
 Character assigned \*A

Certificate (if required)

© 2019

Lloyd's Register  
Foundation

IRON447-0364



*'Glencoyr'*

*"San Lorenzo" 2259/*



© 2019

Lloyd's Register  
Foundation