

ANNUAL SURVEYS.

No. 2257 Survey held at Liverpool Date Nov^r 14th 1870
 on the Iron Ship "Michael Scott" Master W. Llewellyn
 Tonnage 1198 Built at London When built 1864 - 4 m^{ts}
 By whom built Pennie Owners C. J. Fox
 Port belonging to London Destined Voyage Galle
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock and afloat

Last Survey, No. 7382 Port of Iron.

Classed *A\
 (S.S. No. 69) 69

The present Condition of the

Decks Good
 Waterways "
 Comings "
 Upper Deck Beams & Fastenings Iron
 Lower Deck Beams & Fastenings Good
 Planksheers Where
 Sheerstrakes seen
 Topsides
 Wales
 Plank (Bottom) and Counter painted

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings Iron
 Ditto ditto at other places Good
 Keelsons Where
 Clamps and Shelves seen
 Ceiling
 Rudder
 Copper Cement When put on 1864

Windlass and Capstan Good
 Pumps "
 Boats Good and Sufficient
 Masts, Yards, &c. "
 Sails Good and Complete
 Anchors No. of 3 B. 1 S. 2 R.
 Cables Good and Complete
 Hawseers and Warps Good
 Standing & Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now alone, bottom painted. She is in good Condition, and in my opinion eligible to remain as Classed *A\.

Committee's Minute Liverpool 27th December, 1870

Character assigned

*A\ BBR

J. F. Light.

Certificate (if required)

No. 669 Survey held at Liverpool Date Dec^r 5th 1870
 on the Iron Ship "Compta" Master Logan
 Tonnage 1053 Built at Port Glasgow When built 1864 - 3 m^{ts}
 By whom built Duncan Owners C. Bates
 Port belonging to Liverpool Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock and afloat

Last Survey, No. 7775 Port of Iron.

Classed *A\
 (S.S. No. 64/70)

The present Condition of the

Decks Good
 Waterways "
 Comings "
 Upper Deck Beams & Fastenings Iron
 Lower Deck Beams & Fastenings Good
 Planksheers Where
 Sheerstrakes seen
 Topsides
 Wales
 Plank (Bottom) and Counter painted

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings Iron
 Ditto ditto at other places Good
 Keelsons Where
 Clamps and Shelves seen
 Ceiling
 Rudder
 Copper Cement When put on 1864

Windlass and Capstan Good
 Pumps "
 Boats Good and Sufficient
 Masts, Yards, &c. "
 Sails Good and Complete
 Anchors No. of 3 B. 1 S. 2 R.
 Cables Good where seen
 Hawseers and Warps "
 Standing & Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now alone, bottom scraped and painted. - She is now in good Condition, and in my opinion eligible to remain as Classed *A\.

Committee's Minute Liverpool 27th December, 1870

Character assigned

*A\ BBR

J. F. Light.

Certificate (if required).

"Michael Scott"
"22.593"
"Campta"



© 2019

Lloyd's Register
Foundation