

ANNUAL SURVEYS.

8566

~~7756~~

No. 57 Survey held at London Date 12th Dec^r 21st 1870
 on the Ship Saint Magnus Master L. Walker
 Tonnage 1262 Built at Liverpool When built 1864
 By whom built Royden Owners Rankin & Co
 Port belonging to Glasgow Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock Thames Dry dock

Rev. 22.12.70

Last Survey, No. 7756 Port of Iron Classed *A.1.
 present Condition of the

| | <u>good</u> | <u>Treenails</u> | <u>Rivets where seen</u> | <u>good</u> | <u>Windlass and Capstan</u> | <u>in good order</u> |
|-------------------------------|-------------|--------------------------------------|--------------------------|------------------------------------|-----------------------------|----------------------|
| Waterways | ✓ | Breasthooks and Stemson | ✓ | Pumps | ✓ | ✓ |
| Platings | ✓ | Transoms, Pointers, and Crutches | ✓ | Boats | ✓ | ✓ |
| Upper Deck Beams & Fastenings | ✓ | Timbers of the Frame at the Openings | ✓ | Masts, Yards, &c. | ✓ | ✓ |
| Lower Deck Beams & Fastenings | ✓ | Ditto ditto at other places | ✓ | Sails | ✓ | ✓ |
| Keelsons | ✓ | Keelsons | ✓ | Anchors No. of <u>3 V 1 S. 2 K</u> | ✓ | ✓ |
| Strakes | ✓ | Clamps and Shelves | ✓ | Cables | ✓ | ✓ |
| Sides | ✓ | Ceiling | ✓ | Hawsers and Warps | ✓ | ✓ |
| Bottom | ✓ | Rudder <u>efficient</u> | ✓ | Standing & Running Rigging | ✓ | ✓ |
| Bottom (Bottom) and Counter | ✓ | Copper | When put on | | | |

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good.

Cleaned and recoated the bottom.
She is now in good condition and I am of opinion is
entitled to remain as Class *A.1.
Samuel Presious

Committee's Minute 24th Dec^r 1870
 Character assigned *A.1. W.H.

Certificate (if required)

No. 614 Survey held at London Date Dec 6th 15th 1870
 on the Ship Star of Greece Master Geo. Shale
 Tonnage 1289 Built at Belfast When built 1868
 By whom built Harland Owners Corry & Co
 Port belonging to Belfast Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock

Last Survey, No. 7897 Port of Iron Classed *A.1.
 present Condition of the

| | <u>good</u> | <u>Treenails</u> | <u>Rivets where seen</u> | <u>good</u> | <u>Windlass and Capstan</u> | <u>in good order</u> |
|-------------------------------|-------------|--------------------------------------|--------------------------|------------------------------------|-----------------------------|----------------------|
| Waterways | ✓ | Breasthooks and Stemson | ✓ | Pumps | ✓ | ✓ |
| Platings | ✓ | Transoms, Pointers, and Crutches | ✓ | Boats | ✓ | ✓ |
| Upper Deck Beams & Fastenings | ✓ | Timbers of the Frame at the Openings | ✓ | Masts, Yards, &c. | ✓ | ✓ |
| Lower Deck Beams & Fastenings | ✓ | Ditto ditto at other places | ✓ | Sails | ✓ | ✓ |
| Keelsons | ✓ | Keelsons | ✓ | Anchors No. of <u>3 V 1 S. 2 K</u> | ✓ | ✓ |
| Strakes | ✓ | Clamps and Shelves | ✓ | Cables | ✓ | ✓ |
| Sides | ✓ | Ceiling | ✓ | Hawsers and Warps | ✓ | ✓ |
| Bottom | ✓ | Rudder <u>efficient</u> | ✓ | Standing & Running Rigging | ✓ | ✓ |
| Bottom (Bottom) and Counter | ✓ | Copper | When put on | | | |

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good.

Cleaned the bottom, and recoated it with McGowan's Patent Composition
As far as seen she is in good condition, and I am of opinion
she is entitled to remain as
Class *A.1.
Samuel Presious

Committee's Minute 24th Dec^r 1870
 Character assigned *A.1. W.H.

Certificate (if required).

IRON 447-0371

Paul Magnus
Harvard



© 2019

Lloyd's Register
Foundation