

ANNUAL SURVEYS.

No. 22622 Survey held at Liverpool Date Dec 13th 1870
 on the S. Ship British Sovereign Master Jackson
 Tonnage 1345 Built at Bark When built 1864-10th Mo.
 By whom built Robinson Owners British Ship Owners Co.
 Port belonging to Liverpool Destined Voyage Mullbourn
 If Surveyed Afloat or in Dry Dock Brunswick Dry Dock

Last Survey, No. 6694 Port of Iron.

Classed * A 1
18th Sept. 1868

The present Condition of the			
Decks	<u>Good</u>	Rivets	<u>Good</u>
Waterways		Treenails	
Comings		Breasthooks and Stemson	
Upper Deck Beams & Fastenings		Transoms, Pointers, and Crutches	
Lower Deck Beams & Fastenings	<u>When</u>	Timbers of the Frame at the Openings	
Planksheers		Ditto ditto at other places	<u>When</u>
Sheerstrakes		Keelsons	
Topsides		Clamps and Shelves	
Wales		Ceiling	
Plate		Rudder	<u>Seen</u>
Plank (Bottom) and Counter	<u>Seen</u>	Copper	<u>When put on</u>
			<u>64</u>
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways	<u>Good</u>

The bottom cleaned and painted. She is now when seen in good condition and in my opinion eligible to remain as classed

Committee's Minute Liverpool 20th January 71

Character assigned * A 1

Certificate (if required)

No. 103 Survey held at Liverpool Date Jan 13th 1871
 on the S. Ship Hartell Master A. Courtney
 Tonnage 1224 Built at Glasgow When built 1864-3rd Mo.
 By whom built Barclay Owners W. T. T. T.
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Brunswick Dry Dock

Last Survey, No. 6706 Port of Iron

Classed * A 1
18th Sept. 1868

The present Condition of the			
Decks	<u>Good</u>	Treenails	<u>Good</u>
Waterways		Breasthooks and Stemson	
Comings		Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	
Lower Deck Beams & Fastenings	<u>When</u>	Ditto ditto at other places	<u>When</u>
Planksheers		Keelsons	
Sheerstrakes		Clamps and Shelves	
Topsides		Ceiling	
Wales		Rudder	<u>Seen</u>
Plate		Copper	<u>When put on</u>
Plank (Bottom) and Counter	<u>Seen</u>		<u>1864</u>
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways	<u>Good</u>

The bottom cleaned and coated with two coats of paint and one coat of tallow. She is now when seen in good condition and in my opinion eligible to remain as classed

Committee's Minute Liverpool 20th January 71

Character assigned * A 1

Certificate (if required)

"British Sovereign"

"Hartfell" 22622



© 2019

Lloyd's Register
Foundation