

8661

REPORT of SURVEY for REPAIRS.

No. 1342 Survey held at Newcastle Date, first Survey 3rd Dec^r Last Survey 5th Dec^r 1870.
 on the "A. A. Adela" Master _____

Tonnage 322 built at Newcastle When built 1870

By whom built A. Leslie & Co Owners Loring & Co

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock Clarendon's Slip.

Survey, No. 8237 Port Gron Classed 100 A.T.
9.70.

This vessel has been lengthened 50 feet, but the Owners declined to comply with the recommendations of the Committee for the 90 A & grade, as per Secretary's letter of the 2nd December, and she has therefore been lengthened for classification in the Liverpool Registry.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations and Opinion,

Under the above circumstances, I am unable to recommend this vessel for continuance of classification

The Amount of Entry Fee.....£

is received by me,

Special.....

Certificate (if required)

Committee's Minute

Character assigned

7th February 1871

Expunge Character

Notice to owner by owner
 Given to Secretary
 W. Shields
 7/2/71



© 2019

Lloyd's Register Foundation

Committee Minute 17th April 1896.

Character assigned

Insect Three dots

W.D.



© 2019

Lloyd's Register
Foundation