

ANNUAL SURVEYS.

11/2/71
 No. 2257 Survey held at Liverpool Date Feb^{ry} 1881
 on the Iron Ship "Knight Errant" Master Stobie
 Tonnage 1312 Built at Hull When built 1858
 By whom built Liverpool Owners John Stobie & Co. Ltd.
 Port belonging to Liverpool Destined Voyage San Francisco.
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock and afloat.

Last Survey, No. 7771 Port of Iron Classed *A.
S.S. No. 1. 68 40

The present Condition of the

Decks good
 Waterways "
 Comings "
 Upper Deck Beams & Fastenings Iron
 Lower Deck Beams & Fastenings good
 Planksheers where
 Sheerstrakes seen
 Topsides
 Wales
 Plank (Bottom) and Counter Painted

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings Iron
 Ditto ditto at other places good
 Keelsons where
 Clamps and Shelves seen
 Ceiling
 Rudder
 Copper Cement When put on —

Windlass and Capstan good
 Pumps "
 Boats good and sufficient
 Masts, Yards, &c. "
 Sails good and complete.
 Anchors No. of 3 B. 1 S. 2 P.
 Cables good where seen
 Hawseers and Warps good
 Standing & Running Rigging good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done. bottom scraped and painted. She is in good condition and in my opinion eligible to remain as classed *A.

Committee's Minute Liverpool 14th February 1881

Character assigned *A

J. F. Light.

Certificate (if required)

No. 621 Survey held at Liverpool Date Feb^{ry} 28th 1881
 on the Iron Ship "Melbourne" Master Smith
 Tonnage 1636 Built at Greenock When built 1849
 By whom built Liverpool Owners C. Bates.
 Port belonging to Liverpool Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock and afloat.

Last Survey, No. 6109 Port of Iron Classed *A.
S.S. No. 3. 68 68

The present Condition of the

Decks good
 Waterways "
 Comings "
 Upper Deck Beams & Fastenings Iron
 Lower Deck Beams & Fastenings good
 Planksheers where
 Sheerstrakes seen
 Topsides
 Wales
 Plank (Bottom) and Counter Painted

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the Openings Iron
 Ditto ditto at other places good
 Keelsons where
 Clamps and Shelves seen
 Ceiling
 Rudder
 Copper Cement When put on 1868

Windlass and Capstan good
 Pumps "
 Boats good and sufficient
 Masts, Yards, &c. "
 Sails good and complete.
 Anchors No. of 3 B. 1 S. 2 P.
 Cables good where seen.
 Hawseers and Warps good
 Standing & Running Rigging good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done. bottom scraped and painted. She is in good condition and in my opinion eligible to remain as classed *A.

Committee's Minute Liverpool 14th February 1881

Character assigned *A


J. F. Light.

Certificate (if required)

ANNUAL SURVEY

William

Thougl & Co



© 2019

Lloyd's Register
Foundation