

REPORT of SURVEY for REPAIRS.

No. 8773 Survey held at London Date, first Survey Feb'y 23^d Last Survey March 1st 1871
 on the Iron Screw Steamer Knapton Hall Master Wm Sheldrake

Tonnage 851 built at Newcastle When built 1840
 By whom built 562 Palmer Owners Dixon &

Port belonging to London Destined Voyage _____

Surveyed Afloat or in Dry Dock Blackwall point dry dock

Key, No. 8348 Port Iron Classed 90. A. 1.
 &c. 9.70

from damage see the Report of Survey,

Four lengths of plating on each bow cut out
 and renewed or made good as before.

The Rudder pinches overhauled, and some of the butts
 of plating recaulked in the bottom, and all put in order
 inside and outside. -

Present Condition of the

Decks	<u>good</u>	Greenails	<u>Rivets where seen good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	<u>"</u>	Breasthooks and Stenson	<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches	<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the openings	<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto Ditto at other places	<u>"</u>	Condition, how ascertained	<u>from the Deck</u>
Planksheers	<u>"</u>	Keelsons	<u>"</u>	Sails	<u>"</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves	<u>"</u>	Anchors No. of	<u>3 & 1 S. 2 K</u>
Topsides	<u>"</u>	Ceiling	<u>"</u>	Cables	<u>"</u>
Wales	<u>"</u>	Rudder	<u>efficient</u>	Hawsers and Warps	<u>"</u>
Blank (Bottom) and Counter	<u>"</u>	Copper	<u>When put on</u>	Standing & Running Rigging	<u>"</u>
		Caulking of	<u>good</u>		
		Bottom, Deck, & Waterways	<u>good</u>		

Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

General Observations and Opinion,

She is now in good condition and is in my opinion
 entitled to remain as Class'd 90. A. 1.
Samuel Resions

The Amount of Entry Fee..... £ 2 : - : - is received by me,

2nd 2nd See before } Special.....
 charged } Certificate (if required)

Committee's Minute 7 March 1871

Character assigned 90 A 1

record damage repair

Wm



© 2019

Lloyd's Register
 Foundation

LR 448-0124

Rushmore Hall



© 2019

Lloyd's Register
Foundation