

No. 629 Survey held at London 8790 Date Feb'y 20 27 1871 34450
 on the Iron Ship Star of Scotia Master John Smith
 Tonnage 999 Built at Belfast When built 1864
 By whom built Harland Owners Corry & Co
 Port belonging to Belfast Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock East India Docks & Wigram's Dry Dock

Last Survey, No. 8100 Port of Port Classified A. 1. S.S. no 168
670

The present Condition of the

Decks <u>good</u>	Treenails <u>Rivets where seen good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>✓</u>	Breasthooks and Stemson <u>✓</u>	Pumps <u>✓</u>
Comings <u>✓</u>	Transoms, Pointers, and Crutches <u>✓</u>	Boats <u>✓</u>
Upper Deck Beams & Fastenings <u>✓</u>	Timbers of the Frame at the Openings <u>✓</u>	Masts, Yards, &c. <u>✓</u>
Lower Deck Beams & Fastenings <u>✓</u>	Ditto ditto at other places <u>✓</u>	Sails <u>✓</u>
Planksheers <u>✓</u>	Keelsons <u>✓</u>	Anchors No. of <u>3 & 1 S. 2 K</u> <u>✓</u>
Sheerstrakes <u>✓</u>	Clamps and Shelves <u>✓</u>	Cables <u>✓</u>
Topsides <u>✓</u>	Ceiling <u>✓</u>	Hawsers and Warps <u>✓</u>
Wales <u>✓</u>	Rudder <u>efficiently</u> <u>✓</u>	Standing & Running Rigging <u>✓</u>
Plank (Bottom) and Counter <u>✓</u>	Copper <u>When put on</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good
Surveyed with first class on board

Cleaned and recrated the bottom.

As far as seen she is in good condision and I am of opinion
is entitled to remain at Chapol

Committee's Minute 3rd March 1871

Character assigned A 1 87

Samuel Pepys
 Register
 Certificate (if required).