

No. 3295 Survey held at

on the Iron Ship "Loch Awe" Master

Date Feb 14. 6. 25 18 71

Tonnage 1053 Built at

Glasgow

When built

1869

By whom built

Barclay

Owners

J & R. Wilson

Port belonging to

Glasgow

Destined Voyage

Batavia

If Surveyed Afloat or in Dry Dock

Inghis Slip

Last Survey, No.

7930

Port of

Iron

Classed

* A 1
5.70

The present Condition of the

Decks

good

Ironails

Rivets

good

Windlass and Capstan

good

Waterways

Breasthooks and Stemson

Pumps

Comings

Transoms, Pointers, and Crutches

Boats

and

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Masts, Yards, &c.

Lower Deck Beams & Fastenings

where

Do Do at other places

where

Sails

efficient

Planksheers

painted

Keelsons

Clamps and Shelves

Anchors No. of 3B/S 2K

where

Sheerstrakes

dr

Topsides

dr

Ceiling

Seen

Cables

Wales

dr

Rudder

Hawsers and Warps

Seen

Plank (Bottom) and Counter

painted

Copper

fement When put on

1869

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good where seen

She is now in good and efficient condition, fit in my opinion to remain as classed * A 1.

Committee's Minute

10th March 18 71

Character assigned

* A 1

87

Certificate (if required).

IRON 448-0145