

ANNUAL SURVEYS.

37564

No. 208 Survey held at London Date 14 March 1871
 on the iron ship "Van hoe" Master Frank Pitt
 Tonnage 1383 Built at Port Glasgow When built 1868 - 10 mo
 By whom built Reis Owners Williamson & Co
 Port belonging to Liverpool Destined Voyage Calcutta (via Liverpool)
 If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 8095 Port of Iron. Classed ~~SA~~ 6.70
~~7.59~~

The present Condition of the

Decks	Tree nails <i>Rivets</i>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Stoffs	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <i>Iron</i> When put on 1868	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways *Good where examined*

Upper waterways cemented. Bottom cleaned and coated with M. S. Smith's composition. Is now in good and efficient condition, and in my opinion eligible to remain as

Committee's Minute 28th March 1871

Character assigned

*A 1

JRW

M. H. Turner

Certificate (if required)

No. 288 Survey held at London Date 27 March 1871
 on the iron ship "Duke of Argyll" Master J. M. Lean
 Tonnage 960 Built at Dumbarton When built 1865 - 10 mo
 By whom built Rankin Owners Montgomerie & Co
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 7730 Port of Iron. Classed ~~SA~~ 2.70
 (S.S. 19-70)

The present Condition of the

Decks	Tree nails <i>Rivets</i>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Stoffs	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <i>Iron</i> When put on 1865	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways *Good where examined*

Bottom cleaned and coated with patent composition. Is now in good and efficient condition and in my opinion eligible to remain as

Committee's Minute 28th March 1871

Character assigned

*A 1

JRW

M. H. Turner

Certificate (if required).