

ANNUAL SURVEYS.

No. 2245 Survey held at Liverpool Date Feb - 13 to 24 18 71
 on the Ship "Bohelle" Master P. Meldrum
 Tonnage 1286 Built at St. Glasgow When built 1868 - 9 mo
 By whom built Duncan Owners P. Cuthbert
 Port belonging to Greenock Destined Voyage India
 Surveyed Afloat or in Dry Dock Afloat in Clarence Graving dock

Last Survey, No. 6554 Port of Iron.

Classed * A 1

The present Condition of the

Decks	Transoms <u>Revels</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>Good</u>
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>seen</u>	Timbers of the Frame at the Openings	Masts, Yards, &c. <u>L</u>
Lower Deck Beams & Fastenings	Ditto ditto at other places <u>seen</u>	Sails
Planksheers	Keelsons	Anchors No. of <u>Eight</u>
Sheerstrakes	Clamps and Shelves <u>Good where</u>	Cables <u>where</u>
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging <u>seen</u>
Plank (Bottom) and Counter	Copper <u>Cen</u> When put on <u>68</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Satisfactory

The bottom scraped & painted. Is now in good condition
In my opinion eligible to remain as Classed -

Committee's Minute Liverpool 14th April 1871.

Character assigned * A 1

E. C. Wheeler

Certificate (if required)

No. 415 Survey held at Liverpool. Date 23 March April 18 71
 on the SHIP "CORLIC" Master Stevenson
 Tonnage 844 Built at St. Glasgow When built 1868. 6 mo
 By whom built Duncan. Owners Leitch & Co
 Port belonging to Greenock. Destined Voyage Melbourne
 Surveyed Afloat or in Dry Dock Canning Bay Dock.

Last Survey, No. 1927 Port of Iron

Classed * A 1 4.70

The present Condition of the

Decks	Transoms <u>Revels</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cen</u> When put on <u>1868</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Bottom scraped and painted. Is now in good condition. and
in my opinion eligible to remain as classed.

Committee's Minute Liverpool 14th April 1871.

Character assigned * A 1

James Indee

Certificate (if required).

IRON 1448-0282

"Rozelle"
72.757
"Carla"



© 2019

Lloyd's Register
Foundation